

County of Harnett  
Building Inspections Department  
Planning Services

Certificate of Compliance:  Occupancy:

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett, and the North Carolina State Building Codes. For the following:

Use Classification: Residential

**Permit Numbers**

Name: Weatherly Homes

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Address: 4133 Claborn Rd  
Coats

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

Date: 3-10-10

Building Official: Ken Slatt

08-50020659

ADDRESS : 4133 ABBATTIOR RD SUBDIV:  
CONTRACTOR : WEATHERLY HOMES INC PHONE : (919) 639-9965  
OWNER : RAYMOND JR LEE WILLIAM PHONE :  
PARCEL : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----  
PREMISE # 11173864.

*Called Progress @ 7:28 AM*

STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 01 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
B103 02	9/22/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289
	9/22/08	AE	Close blocks turned sideways in front porch foundation wall. The crawl space and the front porch crawl space shall be separate and must have a sealed access door to the porch crawl space. See the attached code reference.
A814 01	9/22/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001680271
	10/02/08	AP	4133 abattoir rd
B105 01	9/24/08	KS	R*OPEN FLOOR VRU #: 001681718
	9/24/08	AP	
E207 02	10/15/08	TI	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001693233
	10/15/08	CA	
E207 01	10/15/08	KS	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001691922
	10/15/08	AP	need premise number
R425 01	10/28/08	KS	FOUR TRADE ROUGH IN VRU #: 001698166
	10/28/08	DA	1. House requires house wrap 2. No test on plumbing 3. Boot missing on vent
R425 02	10/30/08	KS	FOUR TRADE ROUGH IN VRU #: 001698935
	10/30/08	AP	
I129 01	11/07/08	KS	R*INSULATION INSPECTION VRU #: 001702323
	11/07/08	AP	
H824 01	9/17/09	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001823615
	9/17/09	DA	T/S: 09/17/2009 08:43 AM SSTEWARD ----- T/S: 09/17/2009 08:43 AM SSTEWARD ----- PER JAMES MANHART OP ON HOLD - NEEDS WATER LINE CHECK.
H824 02	3/01/10	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001889715
	3/01/10	AP	T/S: 03/02/2010 10:40 AM SSTEWARD ----- T/S: 03/02/2010 10:40 AM SSTEWARD -----
R429 01	3/05/10	KS	FOUR TRADE FINAL VRU #: 001890367

CONTINUED ONTO NEXT PAGE

ADDRESS : 4133 A LATTUOIR RD  
CONTRACTOR : WEATHERLY HOMES INC  
OWNER : RAYMOND JR LEE WILLIAM  
PARCEL : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)

SUBDIV:  
PHONE : (919) 639-9965  
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	3/05/10	DP	1. ✓ In use cover missing on front receptacle 2. ✓ Sheetrock missing in garage beneath fire place box 3. ✓ Dishwasher shall be installed or wire in a box with wirenuts. 4. / gas line not bonded. 5. ✓ Microwave receptacle shall match circuit, ie 20 amp. \$50 re-inspection fee T/S: 03/05/2010 11:05 AM KSLATTUM ----- R429 02 3/10/10 TI FOUR TRADE FINAL TIME: 17:00 VRU #: 001892553 3-10 AP T/S: 03/08/2010 04:17 PM RDCONTE ----- ***SIDE DOOR WILL BE UNLOCKED***

----- COMMENTS AND NOTES -----

ADDRESS . . : 88913 \*UNASSIGNED SUBDIV:  
CONTRACTOR : WEATHERLY HOMES INC PHONE : (919) 639-9965  
OWNER . . : RAYMOND JR LEE WILLIAM PHONE :  
PARCEL . . : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)

STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD  
FLOOD ZONE . . . . : FLOOD ZONE X

PERMIT: CPSF 01 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08 <u>9-03</u>	TI <u>AP</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975

COMMENTS AND NOTES

*Directions on page 2*

*now in HTE*

Application Miscellaneous Information Maintenance

Application number . . . . : 08 50020659
PARCEL NUMBER . . . . . : 07-1602- - -0006- -05-
Address . . . . . : 88913 \*UNASSIGNED

Type information, press Enter.

2=Change 4=Delete 5=Display

Table with columns: Opt, Code, Date, Print, Miscellaneous Information. Rows include BPDN and BPMN entries with dates and descriptions of property information.

More...

F3=Exit F6=Add F12=Cancel

ADDRESS . . : 88913 \*UNASSIGNED  
CONTRACTOR : WEATHERLY HOMES INC  
OWNER . . . : RAYMOND JR LEE WILLIAM  
PARCEL . . . : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----

SUBDIV:  
PHONE : (919) 639-9965  
PHONE :

STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . : 3.00  
SEPTIC - EXISTING? . . . . : NEW SEPTIC  
PROPOSED USE . . . . . : SFD  
WATER SUPPLY . . . . . : COUNTY

PERMIT: CPSF 01 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08 9/03/08	KS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
B103 01	9/08/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037 FOUNDATION

98 DP

COMMENTS AND NOTES

*NOT Built! No portajan*

-----  
ADDRESS . . : 88913 \*UNASSIGNED SUBDIV:  
CONTRACTOR : WEATHERLY HOMES INC PHONE : (919) 639-9965  
OWNER . . . : RAYMOND JR LEE WILLIAM PHONE :  
PARCEL . . . : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----  
-----

**STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD**

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . : 3.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . . : COUNTY  
-----

**PERMIT: CPSF 01 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
A814 01	9/22/08	TI	ADDRESS CONFIRMATION VRU #: 001680271
B103 02	<u>9/22/08</u> 9-22	<u>TI</u> AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289

----- COMMENTS AND NOTES -----

ADDRESS . : 88913 \*UNASSIGNED  
CONTRACTOR : WEATHERLY HOMES INC  
OWNER . . : RAYMOND JR LEE WILLIAM  
PARCEL . . : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----

SUBDIV:  
PHONE : (919) 639-9965  
PHONE :

STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . : 3.00  
SEPTIC - EXISTING? . . . . : NEW SEPTIC  
PROPOSED USE . . . . . : SFD  
WATER SUPPLY . . . . . : COUNTY

PERMIT: CPSF 01 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
A814 01	9/22/08	TI	ADDRESS CONFIRMATION VRU #: 001680271
B103 02	9/22/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289
	9/22/08	AE	Close blocks turned sideways in front porch foundation wall. The crawl space and the front porch crawl space shall be separate and must have a sealed access door to the porch crawl space. See the attached code reference.
B105 01	9/24/08	TI	R*OPEN FLOOR VRU #: 001681718

*APK*

COMMENTS AND NOTES



-----  
ADDRESS . . : 88913 \*UNASSIGNED  
CONTRACTOR : WEATHERLY HOMES INC  
OWNER . . . : RAYMOND JR LEE WILLIAM  
PARCEL . . . : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----  
-----

SUBDIV:  
PHONE : (919) 639-9965  
PHONE :

-----  
**STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD**

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . : 3.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . . : COUNTY  
-----

**PERMIT: CPSF 01 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
B103 02	9/22/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289
	9/22/08	AE	Close blocks turned sideways in front porch foundation wall. The crawl space and the front porch crawl space shall be separate and must have a sealed access door to the porch crawl space. See the attached code reference.
A814 01	9/22/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001680271
	10/02/08	AP	4133 abattoir rd
B105 01	9/24/08	KS	R*OPEN FLOOR VRU #: 001681718
	9/24/08	AP	
E207 01	10/15/08	TI	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001691922
	<u>10-15</u>	<u>AP</u>	

-----  
COMMENTS AND NOTES  
-----

ADDRESS : 88913 \*UNASSIGNED  
CONTRACTOR : WEATHERLY HOMES INC  
OWNER : RAYMOND JR LEE WILLIAM  
PARCEL : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----  
PREMISE # 11173864.

SUBDIV:  
PHONE : (919) 639-9965  
PHONE :

STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3.00  
SEPTIC - EXISTING? : NEW SEPTIC  
PROPOSED USE : SFD  
WATER SUPPLY : COUNTY

PERMIT: CPSF 01 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
B103 02	9/22/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289
	9/22/08	AE	Close blocks turned sideways in front porch foundation wall. The crawl space and the front porch crawl space shall be separate and must have a sealed access door to the porch crawl space. See the attached code reference.
A814 01	9/22/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001680271
	10/02/08	AP	4133 abattoir rd
B105 01	9/24/08	KS	R*OPEN FLOOR VRU #: 001681718
	9/24/08	AP	
E207 02	10/15/08	TI	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 0016932:3
	10/15/08	CA	
E207 01	10/15/08	KS	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 0016919:2
	10/15/08	AP	need premise number
R425 01	10/28/08	TI	FOUR TRADE ROUGH IN VRU #: 001698166

10-25 JA

COMMENTS AND NOTES

**Violation Notice  
Do Not Remove**

**Harnett County Inspection Department  
102 East Front St P.O. Box 65  
Lillington, NC 27546  
Phone (910) 814-6421 Fax (910) 893-2793**

App #07-50020659

October 28, 2008

1. House requires house wrap
2. No test on plumbing water distribution or drains.
3. Boot missing on vent.

**Code Enforcement Official**

Signature      Ken Slattum

ADDRESS : 88913 \*UNASSIGNED SUBDIV:  
 CONTRACTOR : WEATHERLY HOMES INC PHONE : (919) 639-9965  
 OWNER : RAYMOND JR LEE WILLIAM PHONE :  
 PARCEL : 07-1602- - -0006- -05-  
 APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
 RIGHT ON OLD STAGE RD, LEFT ON BENSON  
 RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
 RIGHT.  
 T/S: 09/02/2008 03:58 PM VBROWN ----  
 PREMISE # 11173864.

**STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD**  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

**PERMIT: CPSF 01 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
B103 02	9/22/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289
	9/22/08	AE	Close blocks turned sideways in front porch foundation wall. The crawl space and the front porch crawl space shall be separate and must have a sealed access door to the porch crawl space. See the attached code reference.
A814 01	9/22/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001680271
	10/02/08	AP	4133 abattoir rd
B105 01	9/24/08	KS	R*OPEN FLOOR VRU #: 001681718
	9/24/08	AP	
E207 02	10/15/08	TI	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001693233
	10/15/08	CA	
E207 01	10/15/08	KS	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001691922
	10/15/08	AP	need premise number
R425 01	10/28/08	KS	FOUR TRADE ROUGH IN VRU #: 001698166
	10/28/08	DA	1. House requires house wrap 2. No test on plumbing 3. Boot missing on vent
R425 02	10/30/08	TI	FOUR TRADE ROUGH IN VRU #: 001698935
	<u>10-30</u>	<u>AP</u>	

COMMENTS AND NOTES

-----  
ADDRESS . . : 88913 \*UNASSIGNED SUBDIV:  
CONTRACTOR : WEATHERLY HOMES INC PHONE : (919) 639-9965  
OWNER . . . : RAYMOND JR LEE WILLIAM PHONE :  
PARCEL . . . : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----  
PREMISE # 11173864.  
-----

-----  
**STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD**  
FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . . : 3.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . . : COUNTY  
-----

PERMIT: CPSF 01 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
B103 02	9/22/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289
	9/22/08	AE	Close blocks turned sideways in front porch foundation wall. The crawl space and the front porch crawl space shall be separate and must have a sealed access door to the porch crawl space. See the attached code reference.
A814 01	9/22/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001680271
	10/02/08	AP	4133 abattoir rd
B105 01	9/24/08	KS	R*OPEN FLOOR VRU #: 001681718
	9/24/08	AP	
E207 02	10/15/08	TI	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 00169323
	10/15/08	CA	
E207 01	10/15/08	KS	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 00169192
	10/15/08	AP	need premise number
R425 01	10/28/08	KS	FOUR TRADE ROUGH IN VRU #: 001698166
	10/28/08	DA	1. House requires house wrap 2. No test on plumbing 3. Boot missing on vent
R425 02	10/30/08	KS	FOUR TRADE ROUGH IN VRU #: 001698935
	10/30/08	AP	
I129 01	11/07/08	TI	R*INSULATION INSPECTION VRU #: 001702323
	<u>11-07</u>	<u>AP</u>	

-----  
COMMENTS AND NOTES  
-----

ADDRESS : 133 ABATTOIR RD SUBDIV:  
CONTRACTOR : WEATHERLY HOMES INC PHONE : (919) 639-9965  
OWNER : RAYMOND JR LEE WILLIAM PHONE :  
PARCEL : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : ABBATTIOR RD, HWY 210 TOWARD ANGIER,  
RIGHT ON OLD STAGE RD, LEFT ON BENSON  
RD RIGHT ON ABBATTIOR RD, LOT 1/4 MI ON  
RIGHT.  
T/S: 09/02/2008 03:58 PM VBROWN ----  
PREMISE # 11173864.

STRUCTURE: 000 000 63X35 3BDR 2BATH 2CAR GARAGE SFD

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 01 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/03/08	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001670975
	9/03/08	AP	
B103 01	9/08/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001673037
	9/08/08	DP	FOUNDATION foundation not built. need a portajon on site
B103 02	9/22/08	KS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001680289
	9/22/08	AE	Close blocks turned sideways in front porch foundation wall. The crawl space and the front porch crawl space shall be separate and must have a sealed access door to the porch crawl space. See the attached code reference.
A814 01	9/22/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001680271
	10/02/08	AP	4133 abattoir rd
B105 01	9/24/08	KS	R*OPEN FLOOR VRU #: 001681718
	9/24/08	AP	
E207 02	10/15/08	TI	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001693233
	10/15/08	CA	
E207 01	10/15/08	KS	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001691922
	10/15/08	AP	need premise number
R425 01	10/28/08	KS	FOUR TRADE ROUGH IN VRU #: 001698166
	10/28/08	DA	1. House requires house wrap 2. No test on plumbing 3. Boot missing on vent
R425 02	10/30/08	KS	FOUR TRADE ROUGH IN VRU #: 001698935
	10/30/08	AP	
I129 01	11/07/08	KS	R*INSULATION INSPECTION VRU #: 001702323
	11/07/08	AP	
H824 01	9/17/09	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001823616
	9/17/09	DA	T/S: 09/17/2009 08:43 AM SSTEWARD ----- T/S: 09/17/2009 08:43 AM SSTEWARD ----- PER JAMES MANHART OP ON HOLD - NEEDS WATER LINE CHECK.
H824 02	3/01/10	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001889716
	3/01/10	AP	T/S: 03/02/2010 10:40 AM SSTEWARD ----- T/S: 03/02/2010 10:40 AM SSTEWARD -----
R429 01	3/05/10	TI	FOUR TRADE FINAL VRU #: 001890367

ADDRESS : 4133 ABATTOIR RD  
CONTRACTOR : WEATHERLY HOMES INC  
OWNER : RAYMOND JR LEE WILLIAM  
PARCEL : 07-1602- - -0006- -05-  
APPL NUMBER: 08-50020659 CP NEW RESIDENTIAL (SFD)

SUBDIV:  
PHONE : (919) 639-9965  
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
--------	------------------------	----------------	---------------------------------

COMMENTS AND NOTES

Front Receptacle  
Sheetrock beneath Fire box,  
Dishwasher  
gas line Boding.  
25  
with Disconnect  
Microwave Recept