
ADDRESS . . : 80 JAYLIN BLVD
 CONTRACTOR : FAMILY HOME CONSTRUCTION
 OWNER . . . : C&J DEVELOPMENT #4
 PARCEL . . . : 01-0513- - -0217- -04-
 APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --
 JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 <u>7-17-09</u>	TI <u>AP JV</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for an insp. with lots 2 and 3. temp power pole unlikely to be in place. <i>T-pole</i>

COMMENTS AND NOTES

ADDRESS . . : 80 JAYLIN BLVD
 CONTRACTOR : FAMILY HOME CONSTRUCTION
 OWNER . . . : C&J DEVELOPMENT #4
 PARCEL . . . : 01-0513- - -0217- -04-
 APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --
 JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL -----
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS ----- 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325

7-27-09 DA JD Seal all joints in Block work inside & out of foundation

COMMENTS AND NOTES

T-pole passed

Harnett County - Edit Narrative

Functions Help

7/27/2009 11:33:35 AM

Application number, type	08 50020919 CP NEW RESIDENTIAL (SFD)
Property address	80 JAYLIN BLVD

Fill all joints in block work inside & out of foundation wall.

▲ ▼

OK Exit Cancel Copy Insert Delete Time stamp User defaults

ADDRESS . . : 80 JAYLIN BLVD
CONTRACTOR : FAMILY HOME CONSTRUCTION
OWNER . . . : C&J DEVELOPMENT #4
PARCEL . . . : 01-0513- - -0217- -04-
APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --
JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL -----
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS ----- 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09 7/27/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325 Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09 <i>2-29-09</i>	TI <i>APJH</i>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752 <i>T-pole passed</i>

COMMENTS AND NOTES

ADDRESS . . : 80 JAYLIN BLVD
 CONTRACTOR : FAMILY HOME CONSTRUCTION
 OWNER . . . : C&J DEVELOPMENT #4
 PARCEL . . . : 01-0513- - -0217- -04-
 APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --
 JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole7/2009 01:00 PM JHALL -----
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS ----- 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09 7/27/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325 Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09 7/29/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752 t-pole passed09 11:47 AM JHALL -----
P309 01	9/18/09 <u>9-18-09</u>	TI <u>AP JH</u>	R*PLUMB UNDER SLAB VRU #: 001823871

COMMENTS AND NOTES

ADDRESS . . : 80 JAYLIN BLVD SUBDIV: JAYLIN OAKS
CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
OWNER . . . : C&J DEVELOPMENT #4 PHONE : (910) 321-1002
PARCEL . . . : 01-0513- - -0217- -04-
APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --
JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL -----
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS ----- 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09 7/27/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325 Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09 7/29/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752 t-pole passed 09 11:47 AM JHALL -----
P309 01	9/18/09 9/18/09	JH AP	R*PLUMB UNDER SLAB VRU #: 001823871 -----
B111 01	9/23/09 <u>9-23-09</u>	TI <u>AP JV</u>	R*BLDG SLAB INSP VRU #: 001826106 HE CALLED IT A SLAB INSULATION.

----- COMMENTS AND NOTES -----

ADDRESS : 80 JAYLIN BLVD SUBDIV: JAYLIN OAKS
 CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
 OWNER : C&J DEVELOPMENT #4 PHONE : (910) 321-1002
 PARCEL : 01-0513- - -0217- -04-
 APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --
 JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL -----
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS ----- 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09 7/27/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325 Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09 7/29/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752 t-pole passed 09 11:47 AM JHALL -----
P309 01	9/18/09 9/18/09	JH AP	R*PLUMB UNDER SLAB VRU #: 001823871 -----
B111 01	9/23/09 9/23/09	JH AP	R*BLDG SLAB INSP VRU #: 001826106 HE CALLED IT A SLAB INSULATION. -----
R425 01	7/06/10 <i>7-6-10</i>	TI <i>DA JA</i>	FOUR TRADE ROUGH IN VRU #: 001949726

----- COMMENTS AND NOTES -----

ADDRESS : 80 JAYLIN BLVD SUBDIV: JAYLIN OAKS
 CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
 OWNER : C&J DEVELOPMENT #4 PHONE : (910) 321-1002
 PARCEL : 01-0513- - -0217- -04-
 APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --
 JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09 7/27/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325 Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09 7/29/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752 t-pole passed 09 11:47 AM JHALL
P309 01	9/18/09 9/18/09	JH AP	R*PLUMB UNDER SLAB VRU #: 001823871
B111 01	9/23/09 9/23/09	JH AP	R*BLDG SLAB INSP VRU #: 001826106 HE CALLED IT A SLAB INSULATION.
R425 01	7/06/10 7/06/10	JH DA	FOUR TRADE ROUGH IN VRU #: 001949726 Nail all 2 ply truss per drawings . 2) Fire caulk missing throughout house @ top plate. 3) Anchor bolts every 6' & 1' from corners, need engineer letter for red heads. Duct not connected to exhaust fans for bathrooms. Gas line needs to be labeled in attic every 5'. #2 truss missing strapping @ joint 9. 7) Windows @ front door need to be tempered. 8) 10psi on gas lines.
R425 02	7/14/10 <u>7-14-10</u>	TI <i>Up JV</i>	FOUR TRADE ROUGH IN VRU #: 001953645 <i>Item # 2, 3, 7 & 8 were not corrected</i>

COMMENTS AND NOTES

ADDRESS . : 80 JAYLIN BLVD SUBDIV: JAYLIN OAKS
 CONTRACTOR : FAMILY HOME CONSTRUCTION PHONE : (910) 321-1002
 OWNER . . : C&J DEVELOPMENT #4 PHONE : (910) 321-1002
 PARCEL . . : 01-0513- - -0217- -04-
 APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --
 JAYLIN OAKS LOT 4

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL -----
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS ----- 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09 7/27/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325 Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09 7/29/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752 t-pole passed 09 11:47 AM JHALL -----
P309 01	9/18/09 9/18/09	JH AP	R*PLUMB UNDER SLAB VRU #: 001823871 -----
B111 01	9/23/09 9/23/09	JH AP	R*BLDG SLAB INSP VRU #: 001826106 HE CALLED IT A SLAB INSULATION. -----
R425 01	7/06/10 7/06/10	JH DA	FOUR TRADE ROUGH IN VRU #: 001949726 1)Nail all 2 ply truss per drawings . 2)Fire caulk missing throughout house @ top plate. 3)Anchor bolts every 6' & 1' from corners, need engineer letter for red heads. 4)Duct not connected to exhaust fans for bathrooms. 5)Gas line needs to be labeled in attic every 5'. 6)A2 truss missing strapping @ joint 9. 7)Windows @ front door need to be tempered. 8)10psi on gas lines.
R425 02	7/14/10 <u>7-14-10</u>	TI <i>DA JW</i>	FOUR TRADE ROUGH IN VRU #: 001953645
R325 01	7/15/10 <u>7-15-10</u>	TI <i>DA JW AP</i>	THREE TRADE ROUGH IN VRU #: 001954551 Please schedule for after 12 noon inspection. Thx, Steve 987-2020 <i>check tempered windows on both sides of front door</i>

COMMENTS AND NOTES
@ final

Complete Engineering & Consulting, PLLC

4721 Ray Road
Spring Lake, North Carolina 28390
910-497-6703 Fax: 910-497-5351

July 8, 2010

From: Michael A. Cavnar P.E.
Engineer Consultant

To: Family Home Construction, Inc
2653 Hope Mills Road
Fayetteville, N.C. 28306

RE: Lot # 4 Jaylin Oaks.

On 7/8/10 an inspection was conducted pertaining to anchor bolt installation and span of anchor bolt. Lot # 4 home is a concrete slab system. Area of concern was not enough anchor bolts used. To correct this problem use 1/2" X 12" anchor bolts around entire perimeter walls of the house and along interior load bearing walls, span 6' or less, 12" from all ends. The interior load bearing walls must also have the wet set method. We need to install 1/2" X 12" anchor bolts, 4" inches of bolt above finished concrete, 8" embedded in block filled cells or slab. Drill holes, insert anchor bolt, use a two part epoxy (Fastenal) carries several singular tube types part # Unitex O162483 or Redhead A7-0217278. This will bond the anchor bolt with the concrete. Approximately 10 to 15 anchor bolts will be needed around the house.

Sincerely,

Michael A. Cavnar P.E.
Michael A. Cavnar P.E.

#026912

7/7/10
NORTH CAROLINA
PROFESSIONAL
SEAL
28912
ENGINEER
MICHAEL A. CAVNAR
Michael A. Cavnar

ADDRESS : 80 JAYLIN BLVD
 CONTRACTOR : FAMILY HOME CONSTRUCTION
 OWNER : C&J DEVELOPMENT #4
 PARCEL : 01-0513- - -0217- -04-
 APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
 LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
 LESS AND TURN ON CREEKSVILLE CHURCH RD
 TIL YOU COME TO SUBD.
 T/S: 09/15/2008 12:03 PM DJOHNSON --
 JAYLIN OAKS LOT 4

SUBDIV: JAYLIN OAKS
 PHONE : (910) 321-1002
 PHONE : (910) 321-1002

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00
 SEPTIC - EXISTING? : NEW
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681
	7/17/09	AP	please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL
A814 01	7/23/09	FB	ADDRESS CONFIRMATION VRU #: 001798594
	7/23/09	AP	T/S: 07/23/2009 04:38 PM FBURGESS 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325
	7/27/09	DA	Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752
	7/29/09	AP	t-pole passed 09 11:47 AM JHALL
P309 01	9/18/09	JH	R*PLUMB UNDER SLAB VRU #: 001823871
	9/18/09	AP	
B111 01	9/23/09	JH	R*BLDG SLAB INSP VRU #: 001826106
	9/23/09	AP	HE CALLED IT A SLAB INSULATION.
R425 01	7/06/10	JH	FOUR TRADE ROUGH IN VRU #: 001949726
	7/06/10	DA	1)Nail all 2 ply truss per drawings . 2)Fire caulk missing throughout house @ top plate. 3)Anchor bolts every 6' & 1' from corners, need engineer letter for red heads. 4)Duct not connected to exhaust fans for bathrooms. 5)Gas line needs to be labeled in attic every 5'. 6)A2 truss missing strapping @ joint 9. 7)Windows @ front door need to be tempered. 8)10psi on gas lines.
R425 02	7/14/10	JH	FOUR TRADE ROUGH IN VRU #: 001953645
	7/14/10	DP	Items # 2,3,7 & 8 from previous violations were not corrected
R325 01	7/15/10	JH	THREE TRADE ROUGH IN VRU #: 001954551
	7/15/10	AP	Please schedule for after 12 noon inspection. Thx, Steve 987-2020 Check tempered windows on both sides of front door @ final inspection.
I129 01	7/19/10	TI	R*INSULATION INSPECTION VRU #: 001955921
	7-19-10	AP JW	ready for insulation inspection

COMMENTS AND NOTES

ADDRESS : 80 JAYLIN BLVD
CONTRACTOR: FAMILY HOME CONSTRUCTION
OWNER : C&J DEVELOPMENT #4
PARCEL : 01-0513- - -0217- -04-
APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 210 TOWARDS FAYETTEVILLE, TURN RIGHT AT
LIGHT ONTO RAY RD, GO DOWN 1 MILES OR
LESS AND TURN ON CREEKSVILLE CHURCH RD
TIL YOU COME TO SUBD.
T/S: 09/15/2008 12:03 PM DJOHNSON --
JAYLIN OAKS LOT 4

SUBDIV: JAYLIN OAKS
PHONE : (910) 321-1002
PHONE : (910) 321-1002

STRUCTURE: 000 000 74X53 CRAWL 3BED/2BATH W/GAR & PATIO

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/17/09 7/17/09	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001795681 please schedule for am insp. with lots 2 and 3. temp power pole unlikely to be in place. no t-pole 7/2009 01:00 PM JHALL
A814 01	7/23/09 7/23/09	FB AP	ADDRESS CONFIRMATION VRU #: 001798594 T/S: 07/23/2009 04:38 PM FBURGESS 80 JAYLIN BLVD SPRING LAKE, NC 28390 LOT 4
B103 01	7/27/09 7/27/09	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001800325 Fill all joints in block work inside & out of foundation wall.
B103 02	7/29/09 7/29/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001801752 t-pole passed 09 11:47 AM JHALL
P309 01	9/18/09 9/18/09	JH AP	R*PLUMB UNDER SLAB VRU #: 001823871
B111 01	9/23/09 9/23/09	JH AP	R*BLDG SLAB INSP VRU #: 001826106 HE CALLED IT A SLAB INSULATION.
R425 01	7/06/10 7/06/10	JH DA	FOUR TRADE ROUGH IN VRU #: 001949726 1)Nail all 2 ply truss per drawings . 2)Fire caulk missing throughout house @ top plate. 3)Anchor bolts every 6' & 1' from corners, need engineer letter for red heads. 4)Duct not connected to exhaust fans for bathrooms. 5)Gas line needs to be labeled in attic every 5'. 6)A2 truss missing strapping @ joint 9. 7)Windows @ front door need to be tempered. 8)10psi on gas lines.
R425 02	7/14/10 7/14/10	JH DP	FOUR TRADE ROUGH IN VRU #: 001953645 Items # 2,3,7 & 8 from previous violations were not corrected
R325 01	7/15/10 7/15/10	JH AP	THREE TRADE ROUGH IN VRU #: 001954551 Please schedule for after 12 noon inspection. Thx, Steve 987-2020 Check tempered windows on both sides of front door @ final inspection.
I129 01	7/19/10 7/19/10	JH AP	R*INSULATION INSPECTION VRU #: 001955921 ready for insulation inspection

ADDRESS : 80 JAYLIN BLVD
CONTRACTOR : FAMILY HOME CONSTRUCTION
OWNER : C&J DEVELOPMENT #4
PARCEL : 01-0513- - -0217- -04-
APPL NUMBER: 08-50020919 CP NEW RESIDENTIAL (SFD)

SUBDIV: JAYLIN OAKS
PHONE : (910) 321-1002
PHONE : (910) 321-1002

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	8/10/10 8/10/10	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001968510 T/S: 08/11/2010 11:22 AM SZIMMER T/S: 08/11/2010 11:22 AM SZIMMER
R429 01	8/03/10 <u>9.3-10</u>	TI <u>AP JH</u>	FOUR TRADE FINAL VRU #: 001977669 WOULD LIKE THIS IN THE MORNING.

COMMENTS AND NOTES

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: ___ Occupancy:

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Permit Numbers

Name: Family Home Construction

Building: _____

Electrical: _____

Address: 80 Jaylin Blvd

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

Date: 9-3-10

Building Official: _____

James Hill

81608005-80