

October 8, 2008

www.harnett.org

Harnett County Government Complex 307 Cornelius Harnett Boulevard Lillington, NC 27546

ph: 910-893-7547 fax: 910-893-9371

Wynn Construction 2550 Capitol Drive, Suite 105 Creedmoor, NC 27532

Tingen Pointe - Lt 41

Re: Status of Improvement Permit Application #08-5-21024

To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.
1. Property lines/corners not marked or labeled (\$25.00 fee incurred)
2. House corners not marked or labeled (\$25.00 fee incurred)
3. Directions not clear to property (\$25.00 fee incurred)
4. Property needs brush or vegetation removed
5. Backhoe pits required
X_6. Other – Due a to storm pond located on this lot, your consultant needs to provide proposed septic and repair layout.

Your application will be put on hold until the selected items above have been addressed. When completed please **call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Je West, R. S.

Environmental Health Specialist

Harnett County Department of Public Health

JW/sgs

Copy: Central Permitting