

www.harnett.org

Harnett County Government Complex 307 Cornelius Harnett Boulevard Lillington, NC 27546

December 17, 2008

ph: 910-893-7547 fax: 910-893-9371

Wynn Construction 2550 Capital Drive, Suite 105 Creedmoor, NC 27522

Pioneer Farms
Re: Status of Improvement Permit Application #08-5-21233, #08-5-21234, #08-5-21235
Lts. 13,14,15

To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Improvent evaluation could not be completed for one or more of the following reasons.	nent Permit. The
1. Property lines/corners not marked or labeled (\$25.00 fee incurred)	
2. House corners not marked or labeled (\$25.00 fee incurred)	
3. Directions not clear to property (\$25.00 fee incurred)	
4. Property needs brush or vegetation removed	
5. Backhoe pits required	
X6. Other – Due to the small septic easement and soil conditions, you will a consultant provide proposed septic and repair system.	need to have your soil

Your application will be put on hold until the selected items above have been addressed. When completed please **call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Joe West, R. S.

Environmental Health Specialist Harnett County Department of Public Health

JW/sgs

Copy: Central Permitting