

ADDRESS : 177 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -49-
APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : CAROLINA OAKS S/D LOT 49
HWY 401 TOWARD FAYETTEVILLE TURN LEFT
ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
WILL LUCAS RD TURN RIGHT INTO S/D LOT
ON LEFT JB

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09 <u>6/19/09</u>	TI <u>AP DT</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661 PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.

----- COMMENTS AND NOTES -----

ADDRESS : 177 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -49-
APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : CAROLINA OAKS S/D LOT 49
HWY 401 TOWARD FAYETTEVILLE TURN LEFT
ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
WILL LUCAS RD TURN RIGHT INTO S/D LOT
ON LEFT JB

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661
	6/09/09	AP	PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.
A814 01	6/16/09	TI	ADDRESS CONFIRMATION VRU #: 001781921
B103 01	<u>6/16/09</u> <i>6-16-09</i>	<u>TI</u> <i>APBS</i>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001781939

----- COMMENTS AND NOTES -----

ADDRESS : 177 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -49-
APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : CAROLINA OAKS S/D LOT 49
HWY 401 TOWARD FAYETTEVILLE TURN LEFT
ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
WILL LUCAS RD TURN RIGHT INTO S/D LOT
ON LEFT JB

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661
	6/09/09	AP	PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.
B103 01	6/16/09	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001781939
	6/16/09	AP	
A814 01	6/16/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001781921
	6/18/09	AP	177 CAROLINA OAKS CIR LOT 49 LINDEN 28356
P309 01	6/19/09	TI	R*PLUMB UNDER SLAB VRU #: 001783737

6/19/09 *AP DT*

COMMENTS AND NOTES

Come After Lunch

ADDRESS : 177 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -49-
APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : CAROLINA OAKS S/D LOT 49
HWY 401 TOWARD FAYETTEVILLE TURN LEFT
ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
WILL LUCAS RD TURN RIGHT INTO S/D LOT
ON LEFT JB

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661
	6/09/09	AP	PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.
B103 01	6/16/09	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001781939
	6/16/09	AP	
A814 01	6/16/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001781921
	6/18/09	AP	177 CAROLINA OAKS CIR LOT 49 LINDEN 28356
P309 01	6/19/09	DT	R*PLUMB UNDER SLAB VRU #: 001783737
	6/19/09	AP	
B111 01	6/23/09	TI	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001784842
	<u>6/23/09</u>	<u>AP</u>	PLEASE GO FIRST THING IN THE MORNING.

COMMENTS AND NOTES

ADDRESS : 177 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -49-
APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : CAROLINA OAKS S/D LOT 49
HWY 401 TOWARD FAYETTEVILLE TURN LEFT
ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
WILL LUCAS RD TURN RIGHT INTO S/D LOT
ON LEFT JB

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661
	6/09/09	AP	PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.
B103 01	6/16/09	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001781939
	6/16/09	AP	
A814 01	6/16/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001781921
	6/18/09	AP	177 CAROLINA OAKS CIR LOT 49 LINDEN 28356
P309 01	6/19/09	DT	R*PLUMB UNDER SLAB VRU #: 001783737
	6/19/09	AP	
B111 01	6/23/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001784842
	6/23/09	AP	PLEASE GO FIRST THING IN THE MORNING.
R425 01	7/21/09	TI	FOUR TRADE ROUGH IN VRU #: 001797345

7-21-09 PAJH

COMMENTS AND NOTES

Violation Notice

Do Not Remove

Harnett County Inspection Department
Jimmy Hall (910)984-4768

Permit #09-50022021

Date: 7/21/09

- 1) Missing 2 anchor bolts in garage @ bed 4 closet wall.
- 2) Missing anchor bolts throughout house no more than 6' apart & 1' from ends.
- 3) Strap water lines @ water heater every 32".
- 4) Osb loose to the left of window in bed 4.
- 5) Nail guards on water lines in master bed closet @ bottom plate.
- 6) 3' head of water on drain lines.
- 7) Strap duct for trunk line every 64" & flex duct every 4'.
- 8) A02,A03 & A04 missing uplift straps on front porch.
- 9) Need to attach 4ply truss per drawings & uplift straps per drawings.
- 10)Rafter can not be wider than ridge beam above spare bath.

ADDRESS : 177 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -49-
APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : CAROLINA OAKS S/D LOT 49
HWY 401 TOWARD FAYETTEVILLE TURN LEFT
ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
WILL LUCAS RD TURN RIGHT INTO S/D LOT
ON LEFT JB

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661
	6/09/09	AP	PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.
B103 01	6/16/09	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001781939
	6/16/09	AP	
A814 01	6/16/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001781921
	6/18/09	AP	177 CAROLINA OAKS CIR LOT 49 LINDEN 28356
P309 01	6/19/09	DT	R*PLUMB UNDER SLAB VRU #: 001783737
	6/19/09	AP	
B111 01	6/23/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001784842
	6/23/09	AP	PLEASE GO FIRST THING IN THE MORNING.
R425 01	7/21/09	JH	FOUR TRADE ROUGH IN VRU #: 001797345
	7/21/09	DA	1)Missing 2 anchor bolts in garage @ bed 4 closet wall. 2)Missing anchor bolts throughout house no more than 6' apart & 1' from ends. 3)Strap water lines @ water heater every 32". 4)Osb loose to left of window in bed 4. 5)Nail guards on water lines in master bed closet bottom p. 6)3' head of water on drain lines. 7)strap duct for trunk lines 64" & flex duct every 4'. 8)A02,A03 & A04 missing uplift straps on front porch. 9)Need to attach 4ply truss per drawings & uplift straps. 10)Rafter can not be wider than ridge beam above spare bath
R425 02	7/23/09	TI	FOUR TRADE ROUGH IN VRU #: 001798772

7/23/09 AP DT

COMMENTS AND NOTES

ADDRESS : 177 CAROLINA OAKS CIR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER : BILL CLARK HOMES LLC
PARCEL : 01-0544- - -0012- -49-
APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : CAROLINA OAKS S/D LOT 49
HWY 401 TOWARD FAYETTEVILLE TURN LEFT
ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
WILL LUCAS RD TURN RIGHT INTO S/D LOT
ON LEFT JB

SUBDIV: CAROLINA OAKS 64 LOTS
PHONE : (252) 355-5805
PHONE :

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
SEPTIC - EXISTING? : NEW
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661
	6/09/09	AP	PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.
B103 01	6/16/09	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001781939
	6/16/09	AP	
A814 01	6/16/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001781921
	6/18/09	AP	177 CAROLINA OAKS CIR LOT 49 LINDEN 28356
P309 01	6/19/09	DT	R*PLUMB UNDER SLAB VRU #: 001783737
	6/19/09	AP	
B111 01	6/23/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001784842
	6/23/09	AP	PLEASE GO FIRST THING IN THE MORNING.
R425 01	7/21/09	JH	FOUR TRADE ROUGH IN VRU #: 001797345
	7/21/09	DA	1)Missing 2 anchor bolts in garage @ bed 4 closet wall. 2)Missing anchor bolts throughout house no more than 6' apart & 1' from ends. 3)Strap water lines @ water heater every 32". 4)Osb loose to left of window in bed 4. 5)Nail guards on water lines in master bed closet bottom p. 6)3' head of water on drain lines. 7)strap duct for trunk lines 64" & flex duct every 4'. 8)A02,A03 & A04 missing uplift straps on front porch. 9)Need to attach 4ply truss per drawings & uplift straps. 10)Rafter can not be wider than ridge beam above spare bath
R425 02	7/23/09	DT	FOUR TRADE ROUGH IN VRU #: 001798772
	7/23/09	AP	
I129 01	7/29/09	TI	R*INSULATION INSPECTION VRU #: 001801786
	<u>7/29/09</u>	<u>AP DT</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 177 CAROLINA OAKS CIR SUBDIV: CAROLINA OAKS 64 LOTS
 CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805
 OWNER : BILL CLARK HOMES LLC PHONE :
 PARCEL : 01-0544- - -0012- -49-
 APPL NUMBER: 09-50022021 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : CAROLINA OAKS S/D LOT 49
 HWY 401 TOWARD FAYETTEVILLE TURN LEFT
 ONTO ELLIOTT BRIDGE RD TURN RIGHT ONTO
 WILL LUCAS RD TURN RIGHT INTO S/D LOT
 ON LEFT JB

STRUCTURE: 000 000 64X43 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001778661
	6/09/09	AP	PLEASE COME IN THE MORNING, BEFORE THE RAIN COMES.
B103 01	6/16/09	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001781939
	6/16/09	AP	
A814 01	6/16/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001781921
	6/18/09	AP	✓ 177 CAROLINA OAKS CIR LOT 49 LINDEN 28356
P309 01	6/19/09	DT	R*PLUMB UNDER SLAB VRU #: 001783737
	6/19/09	AP	
B111 01	6/23/09	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001784842
	6/23/09	AP	PLEASE GO FIRST THING IN THE MORNING.
R425 01	7/21/09	JH	FOUR TRADE ROUGH IN VRU #: 001797345
	7/21/09	DA	1)Missing 2 anchor bolts in garage @ bed 4 closet wall. 2)Missing anchor bolts throughout house no more than 6' apart & 1' from ends. 3)Strap water lines @ water heater every 32". 4)Osb loose to left of window in bed 4. 5)Nail guards on water lines in master bed closet bottom p. 6)3' head of water on drain lines. 7)strap duct for trunk lines 64" & flex duct every 4'. 8)A02,A03 & A04 missing uplift straps on front porch. 9)Need to attach 4ply truss per drawings & uplift straps. 10)Rafter can not be wider than ridge beam above spare bath
R425 02	7/23/09	DT	FOUR TRADE ROUGH IN VRU #: 001798772
	7/23/09	AP	
I129 01	7/29/09	DT	R*INSULATION INSPECTION VRU #: 001801786
	7/29/09	AP	
H824 01	9/21/09	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001825595
	9/21/09	AP	T/S: 09/22/2009 10:43 AM SSTEWARD ----- T/S: 09/22/2009 10:43 AM SSTEWARD -----
R429 01	10/12/09	TI	FOUR TRADE FINAL VRU #: 001834621
	<u>10/12/09</u>	<u>AP DT</u>	

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential

Conditional Use Permit No.: _____

Type of Construction: _____

Building Permit No.: _____

Owner of Building: Bill Clark Homes LLC

Electrical Permit No.: _____

Building Address: 177 Carolina Oaks Cir.

Insulation Permit No.: _____

Zoning District: Linden, NC 28356

Plumbing Permit No.: _____

Zoning Permit No.: _____

Mech. Permit No.: 09-50022021

Envir. C.O. No.: _____

Date: 10/12/09

[Signature]

Building Official

Zoning Official