

July 23, 2009

Harnett County Government Complex
307 W. Cornelius Harnett Boulevard
Lillington, NC 27546

Wynn Construction
2550 Capital Drive, Suite 105
Creedmoor, NC 27522

ph: 910-893-7547
fax: 910-893-9371

**Re: Status of Improvement Permit Application #09-5-22207, #09-5-22208, #09-5-22209
Lts. 53, 55, 56 – Tingen Pointe**

To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Property lines/corners not marked or labeled (*\$25.00 fee incurred*) – *see below
- 2. House corners not marked or labeled (*\$25.00 fee incurred*)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Property needs brush or vegetation removed
- 5. Backhoe pits required – (Lt 55 and Lt 56 only)
- 6. Other

***Lot 53 - Locate front property irons**

***Lot 55 - Locate front left property iron, and back hoe pits will be needed.**

Lot 56 - Back hoe pits needed

Your application will be put on hold until the selected items above have been addressed.
When completed please call 910-893-7547 to confirm that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Bryan McSwain, R. S.
Environmental Health Specialist
Harnett County Department of Public Health

BM/sgs
Copy: Central Permitting