

June 10, 2009

ph: 910-893-7547

fax: 910-893-9371

Wynn Construction
2550 Capital Drive, Suite 105
Creedmoor, NC 27522

**Re: Status of Improvement Permit Application #09-5-22207, #09-5-22208, #09-5-22209
Lts. 53, 55, 56 – Tingen Pointe**

To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Property lines/corners not marked or labeled (*\$25.00 fee incurred*) – *Find all corner irons*
- 2. House corners not marked or labeled (*\$25.00 fee incurred*)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Property needs brush or vegetation removed
- 5. Backhoe pits required
- 6. Other

Your application will be put on hold until the selected items above have been addressed.

When completed please call **910-893-7547** to **confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Bryan McSwain, R. S.
Environmental Health Specialist
Harnett County Department of Public Health

BM/sgs

Copy: Central Permitting