

whomever performing work. Must be owner or licensed contractor. Address, company name & phone must match information on license.

Application # 09-500 22335

Hamett County Central Permitting

PO Box 65 Lillington, NC 27546

910-893-7525 Fax 910-893-2793 www.hamett.org/permits

**Application for Residential Building and Trades Permit**

Owner's Name: E. Leon Whittington Date: 10-12-09

Site Address: 966 Bill Avery Rd., Coats, NC 27021 Phone: 910-897-8949

Directions to job site from Lillington: Hwy 27 E. to Coats. T/L on Bill Avery Rd. Job is 1 mile on Right.

Subdivision: N/A Lot: \_\_\_\_\_

Description of Proposed Work: New single Family Dwelling #Bedrooms: 4

Heated SF 2460 Unheated SF 730 Finished Rec Room? NO Crawl Space  Slab ( )

**General Contractor Information**

Marshall Johnson Construction, Inc 919-427-7111

Building Contractor's Company Name Telephone

283 Banner Blk Rd. Benson, NC 27504 55274

Address License #

[Signature]

Must sign & fill out second page

Signature of Owner/Contractor/Officer(s) of Corporation

**Electrical Permit Information**

Description of Work wire new house Service Size: 200 Amps TPole  no

R.A. Jackson Electric 919-894-5367

Electrical Contractor's Company Name Telephone

9261 Raleigh Rd, Benson, NC 27504 21144

Address License #

Bobby Jackson

Signature of Officer(s) of Corporation

**Mechanical/HVAC Permit Information**

Description of Work Install 2 new units + duct work

Beasley's HVAC 919-894-4248

Mechanical Contractor's Company Name Telephone

57 Wc Beasley Lane, Coats, NC. 27521 9470

Address License #

Brent Beasley

Signature of Officer(s) of Corporation

**Plumbing Permit Information**

Description of Work Plumb new House # Baths 2

Hill's Plumbing 919-580-1148

Plumbing Contractor's Company Name Telephone

103 Collie Dr. Goldsboro, NC 27530 8948

Address License #

May D Hill

Signature of Officer(s) of Corporation

**Insulation Permit Information**

Tri-City Insulation 418 Person St. Fayetteville, NC. 500-408-1012

Insulation Contractor's Company Name & Address Telephone





[The page contains extremely faint and illegible text, likely bleed-through from the reverse side of the document. The text is scattered across the page and does not form any recognizable words or sentences.]