

July 9, 2009

Jeffrey L. Pope  
2568 Old Buies Creek Road  
Angier, NC 27501

**Re: Status of Improvement Permit Application # 09-5-22335**

Dear Mr. Pope,

An attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Property lines/corners not marked or labeled (\$25.00 fee incurred)**
- 2. House corners not marked or labeled (\$25.00 fee incurred)
- 3. Directions not clear to property (\$25.00 fee incurred)
- 4. Property needs brush or vegetation removed
- 5. Backhoe pits may be required**
- 6. Other – Could not locate property irons. Need to have property surveyed to locate property irons, and then restake.**

Your application will be put on hold until the selected items above have been addressed.

When completed please call 910-893-7547 to confirm that the items mentioned have been corrected, we will then reschedule your property for evaluation. I may be reached between the hours of 8:00 – 9:00 a.m. if you have questions.

Sincerely,



James E. Manhart, III, R. S.  
Environmental Health Specialist  
Harnett County Department of Public Health

JEM/sgs

Copy: Central Permitting