

ADDRESS : 580 OMAHA DR
CONTRACTOR : AMERICAN HOMESMITH LLC
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576- - -0088- -78-
APPL NUMBER: 09-50022364 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 580 OMAHA DRIVE TINGEN POINT SUB DIV
#78

SUBDIV: TINGEN POINTE 86LOTS
PHONE : (919) 422-4128
PHONE :

STRUCTURE: 000 000 44X44.5 CRAWL 3BD/2BA W/GAR, PATIO, BN RM

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/22/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840351
	10/22/09	CA	T/S: 10/22/2009 08:00 AM NTART -----
B101 02	10/23/09 <i>10-23-9</i>	TI <i>AP</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840896

COMMENTS AND NOTES

FS

PE
10:05
10-23-9

ADDRESS : 580 OMAHA DR
CONTRACTOR : AMERICAN HOMESMITH LLC
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576- - -0088- -78-
APPL NUMBER: 09-50022364 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 580 OMAHA DRIVE TINGEN POINT SUB DIV
#78

SUBDIV: TINGEN POINTE 86LOTS
PHONE : (919) 422-4128
PHONE :

STRUCTURE: 000 000 44X44.5 CRAWL 3BD/2BA W/GAR, PATIO, BN RM

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/22/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840351
	10/22/09	CA	T/S: 10/22/2009 08:00 AM NTART -----
B101 02	10/23/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840896
	10/23/09	AP	T/S: 10/23/2009 03:43 PM FSPIVEY -----
A814 01	10/27/09	TI	ADDRESS CONFIRMATION VRU #: 001841980
B103 01	10/27/09 <i>10/27/09</i>	TI <i>AP DT</i>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001841998

COMMENTS AND NOTES

ADDRESS : 580 OMAHA DR
CONTRACTOR : AMERICAN HOMESMITH LLC
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576- - -0088- -78-
APPL NUMBER: 09-50022364 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 580 OMAHA DRIVE TINGEN POINT SUB DIV
#78

SUBDIV: TINGEN POINTE 86LOTS
PHONE : (919) 422-4128
PHONE :

STRUCTURE: 000 000-44X44.5 CRAWL 3BD/2BA W/GAR, PATIO, BN RM

FLOOD ZONE : FLOOD_ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW SEPTIC
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/22/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840351
	10/22/09	CA	T/S: 10/22/2009 08:00 AM NTART -----
B101 02	10/23/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840896
	10/23/09	AP	T/S: 10/23/2009 03:43 PM FSPIVEY -----
A814 01	10/27/09	TI	ADDRESS CONFIRMATION VRU #: 001841980
B103 01	10/27/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001841998
	10/27/09	AP	
B105 01	10/30/09	TI	R*OPEN FLOOR VRU #: 001843875

10/30/09 AP-IVR

----- COMMENTS AND NOTES -----

ADDRESS : 580 OMAHA DR
CONTRACTOR : AMERICAN HOMESMITH LLC
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576- - -0088- -78-
APPL NUMBER: 09-50022364 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 580 OMAHA DRIVE TINGEN POINT SUB DIV
#78

SUBDIV: TINGEN POINTE 86LOTS
PHONE : (919) 422-4128
PHONE :

STRUCTURE: 000 000 44X44.5 CRAWL 3BD/2BA W/GAR, PATIO, BN RM

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/22/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840351
	10/22/09	CA	T/S: 10/22/2009 08:00 AM NTART -----
B101 02	10/23/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840896
	10/23/09	AP	T/S: 10/23/2009 03:43 PM FSPIVEY -----
B103 01	10/27/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001841998
	10/27/09	AP	
A814 01	10/27/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001841980
	11/04/09	AP	580 omaha dr lot 78 ----- broadway 27505 T/S: 11/04/2009 04:22 PM TWARD -----
B105 01	10/30/09	MR	R*OPEN FLOOR VRU #: 001843875
	10/30/09	AP	T/S: 10/30/2009 10:53 AM MREARIC -----
R425 01	11/25/09	TI	FOUR TRADE ROUGH IN VRU #: 001854926

11-25-09 DA-MR

COMMENTS AND NOTES

Washer Low
OK to install

ADDRESS : 580 OMAHA DR
 CONTRACTOR : AMERICAN HOMESMITH LLC
 OWNER : THE HARNETT LAND GROUP II LLC
 PARCEL : 03-9576- - -0088- -78-
 APPL NUMBER: 09-50022364 CP NEW RESIDENTIAL (SFD)

SUBDIV: TINGEN POINTE 86LOTS
 PHONE : (919) 422-4128
 PHONE :

DIRECTIONS : 580 OMAHA DRIVE TINGEN POINT SUB DIV
 #78

STRUCTURE: 000 000 44X44.5 CRAWL 3BD/2BA W/GAR, PATIO, BN RM

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/22/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840351
	10/22/09	CA	T/S: 10/22/2009 08:00 AM NTART -----
B101 02	10/23/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840896
	10/23/09	AP	T/S: 10/23/2009 03:43 PM FSPIVEY -----
B103 01	10/27/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001841998
	10/27/09	AP	
A814 01	10/27/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001841980
	11/04/09	AP	580 omaha dr lot 78 ----- broadway 27505 T/S: 11/04/2009 04:22 PM TWARD -----
B105 01	10/30/09	MR	R*OPEN FLOOR VRU #: 001843875
	10/30/09	AP	T/S: 10/30/2009 10:53 AM MREARIC -----
R425 01	11/25/09	MR	FOUR TRADE ROUGH IN VRU #: 001854926
	11/25/09	DA	T/S: 11/25/2009 01:16 PM MREARIC ----- washer box too low ok to insulate
I129 01	12/02/09	TI	R*INSULATION INSPECTION VRU #: 001856414
	<u>12-2-9</u>	<u>AP-MR</u>	
R425 02	12/02/09	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001856848
	<u>12-2-9</u>	<u>AP-MR</u>	T/S: 12/01/2009 02:07 PM NTART -----

COMMENTS AND NOTES

ADDRESS : 580 OMAHA DR SUBDIV: TINGEN POINTE 86LOTS
 CONTRACTOR : AMERICAN HOMESMITH LLC PHONE : (919) 422-4128
 OWNER : THE HARNETT LAND GROUP II LLC PHONE :
 PARCEL : 03-9576- - -0088- -78-
 APPL NUMBER: 09-50022364 CP NEW RESIDENTIAL (SPD)
 DIRECTIONS : 580 OMAHA DRIVE TINGEN POINT SUB DIV
 #78

STRUCTURE: 000 000 44X44.5 CRAWL 3BD/2BA W/GAR, PATIO, BN RM
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/22/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840351
	10/22/09	CA	T/S: 10/22/2009 08:00 AM NTART -----
B101 02	10/23/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840896
	10/23/09	AP	T/S: 10/23/2009 03:43 PM FSPIVEY -----
B103 01	10/27/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001841998
	10/27/09	AP	
A814 01	10/27/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001841980
	11/04/09	AP	✓ 580 omaha dr lot 78 ----- Broadway 27505 T/S: 11/04/2009 04:22 PM TWARD -----
B105 01	10/30/09	MR	R*OPEN FLOOR VRU #: 001843875
	10/30/09	AP	T/S: 10/30/2009 10:53 AM MREARIC -----
R425 01	11/25/09	MR	FOUR TRADE ROUGH IN VRU #: 001854926
	11/25/09	DA	T/S: 11/25/2009 01:16 PM MREARIC ----- washer box too low ok to insulate
I129 01	12/02/09	MR	R*INSULATION INSPECTION VRU #: 001856414
	12/02/09	AP	T/S: 12/02/2009 11:42 AM MREARIC -----
R425 02	12/02/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001856848
	12/02/09	AP	T/S: 12/01/2009 02:07 PM NTART ----- T/S: 12/02/2009 11:44 AM MREARIC -----
H824 01	3/02/10	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001890102
	3/02/10	AP	T/S: 03/03/2010 12:22 PM SSTEWARD ----- T/S: 03/03/2010 12:26 PM SSTEWARD -----
R429 01	3/05/10	TI	FOUR TRADE FINAL VRU #: 001890699

3.5-10 DP-MR

COMMENTS AND NOTES

Bolt Bracing on deck
 Hookup A/C Float Switch

ADDRESS : 580 OMAHA DR
CONTRACTOR : AMERICAN HOMESMITH LLC
OWNER : THE HARNETT LAND GROUP II LLC
PARCEL : 03-9576- - -0088- -78-
APPL NUMBER: 09-50022364 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 580 OMAHA DRIVE TINGEN POINT SUB DIV
#78

SUBDIV: TINGEN POINTE 86LOTS
PHONE : (919) 422-4128
PHONE :

STRUCTURE: 000 000 44X44.5 CRAWL 3BD/2BA W/GAR, PATIO, BN RM

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW SEPTIC

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/22/09	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840351
	10/22/09	CA	T/S: 10/22/2009 08:00 AM NTART -----
B101 02	10/23/09	FS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001840896
	10/23/09	AP	T/S: 10/23/2009 03:43 PM FSPIVEY -----
B103 01	10/27/09	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001841998
	10/27/09	AP	
A814 01	10/27/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001841980
	11/04/09	AP	✓ 580 omaha dr lot 78 ----- broadway 27505 T/S: 11/04/2009 04:22 PM TWARD -----
B105 01	10/30/09	MR	R*OPEN FLOOR VRU #: 001843875
	10/30/09	AP	T/S: 10/30/2009 10:53 AM MREARIC -----
R425 01	11/25/09	MR	FOUR TRADE ROUGH IN VRU #: 001854926
	11/25/09	DA	T/S: 11/25/2009 01:16 PM MREARIC ----- washer box too low ok to insulate
I129 01	12/02/09	MR	R*INSULATION INSPECTION VRU #: 001856414
	12/02/09	AP	T/S: 12/02/2009 11:42 AM MREARIC -----
R425 02	12/02/09	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001856848
	12/02/09	AP	T/S: 12/01/2009 02:07 PM NTART ----- T/S: 12/02/2009 11:44 AM MREARIC -----
H824 01	3/02/10	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001890102
	3/02/10	AP	T/S: 03/03/2010 12:22 PM SSTEWARD ----- T/S: 03/03/2010 12:26 PM SSTEWARD -----
R429 01	3/05/10	MR	FOUR TRADE FINAL VRU #: 001890699
	3/05/10	DP	T/S: 03/05/2010 12:21 PM MREARIC ----- bolt dack bracing to code wire ahu float switch
R429 02	4/13/10	TI	FOUR TRADE FINAL VRU #: 001908953

4-13-10 AP-MR

COMMENTS AND NOTES

65167837
0449 2990

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: _____ Occupancy: _____

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3

Permit Numbers

Name: Harnett Land Group II LLC,

Building: 09-50022364

Address: 580 Omaha

Electrical:

Insulation:

Plumbing:

Mechanical:

MFG Home:

Date: 4-13-10

Building Official: T. Michael Ream