

www.harnett.o

August 27, 2009

BIM Builders, LLC 6187 NC 27 East Coats, NC 27521 Harnett County Government Comple 307 W. Cornelius Harnett Boulevar Lillington, NC 2754

ph: 910-893-754

fax: 910-893-937

Re: Status of Improvement Permit Application #09-5-22642

To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

1.	Property lines/corners not marked or labele	d (\$25.00 fee incurred)
2.	House corners not marked or labeled (\$25)	00 fee incurred)

- \_\_\_\_3. Directions not clear to property (\$25.00 fee incurred)
- 4. Property needs brush or vegetation removed
- \_\_\_\_\_5. Backhoe pits required

\_\_\_X\_\_\_6. Other - see below

As stated in Southeastern Soil & Environmental Associates report for this lot, drip irrigation may be required. Our evaluation of this lot has led to similar conclusions. Please have your soil consultant provide us with a septic system design for this lot.

Your application will be put on hold until the selected items above have been addressed. When completed please call 910-893-7547 to confirm that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely

Oliver Tolksdorf, R. S.

Environmental Health Soil Scientist

Harnett County Department of Public Health

OT/sgs

Copy: Central Permitting