

September 15, 2009

Bradley Built Inc  
466 Stancil Road  
Angier, NC 27501

**Re: Status of Improvement Permit Application #09-5-22718**


To Whom It May Concern,

An attempt was made to evaluate your property for the purpose of issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Property lines/corners not marked or labeled *(\$25.00 fee incurred)*
- 2. House corners not marked or labeled *(\$25.00 fee incurred)*
- 3. Directions not clear to property *(\$25.00 fee incurred)*
- 4. Property needs brush or vegetation removed
- 5. Backhoe pits required
- 6. **Other – Lot was not identified in any way. There was no way to tell if I was on the correct lot or not. Place orange sign on the lot along with lot number so that lot can be identified. Make sure all corner irons and house corners are found and clearly marked. *(\$25.00 return trip fee)***

Your application will be put on hold until the selected items above have been addressed. When completed **please call 910-893-7527 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Joe West, R. S.  
Environmental Health Specialist  
Harnett County Department of Public Health

JW/sgs  
Copy: Central Permitting