
ADDRESS : 580 VALLEY OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-05- -0028- -52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/19/2009 11:14 AM RDCONTE ---
FOREST OAKS PH:3 #165 580 VALLEY OAK
TAKE 27W, T/L ON NURSERY ROAD. T/L ON
WOOD POINT DRIVE. T/R ON KIMBROUGH
DRIVE. T/L ON BLUE OAK. T/L ON VALLEY
OAK.
*****SREMC*****

SUBDIV: FOREST OAKS PH 3 99LOTS
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 45X38 SLAB 3BD/2.5BA W/GAR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED	INSP	DESCRIPTION
COMPLETED	RESULT	RESULTS/COMMENTS	
P309 01	12/02/09 <u>12/2/09</u>	TI <u>AP DT</u>	R*PLUMB UNDER SLAB VRU #: 001856822

COMMENTS AND NOTES

ADDRESS : 580 VALLEY OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-05- -0028- -52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/19/2009 11:14 AM RDCONTE ---
FOREST OAKS PH:3 #165 580 VALLEY OAK
TAKE 27W, T/L ON NURSERY ROAD. T/L ON
WOOD POINT DRIVE. T/R ON KIMBROUGH
DRIVE. T/L ON BLUE OAK. T/L ON VALLEY
OAK.
****SREMC****

SUBDIV: FOREST OAKS PH 3 99LOTS
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 45X38 SLAB 3BD/2.5BA W/GAR

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW TANK

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	12/02/09	DT	R*PLUMB UNDER SLAB VRU #: 001856822
	12/02/09	AP	
B104 01	12/04/09	TI	R*BLDG FOUNDATION SURVEY VRU #: 001857333
	<u>12/14/09</u>	<u>DAIX</u>	We need a monolithic slab inspection, that option was not on the list. Thank You

COMMENTS AND NOTES

Application number, type : 09 50023070 CP NEW RESIDENTIAL (SFD)
Property address : 580 VALLEY OAK DR

- 1. Slab must be insulated.
- 2. Lugs must be squared off and 24 inches wide by plans.
- 3. Bottom of trenches must be 12 inches below grade at all points.

T/S: 12/04/2009 09:50 AM DETAYLOR -----



ADDRESS : 580 VALLEY OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-05-0028-52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)

SUBDIV: FOREST OAKS PH 3 99LOTS
PHONE : (919) 481-0503
PHONE :

DIRECTIONS : T/S: 10/19/2009 11:14 AM RDCONTE ---
FOREST OAKS PH:3 #165 580 VALLEY OAK
TAKE 27W, T/L ON NURSERY ROAD. T/L ON
WOOD POINT DRIVE. T/R ON KIMBROUGH
DRIVE. T/L ON BLUE OAK. T/L ON VALLEY
OAK.
****SREMC****


STRUCTURE: 000 000 45X38 SLAB 3BD/2.5BA W/GAR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	12/02/09	DT	R*PLUMB UNDER SLAB VRU #: 001856822
	12/02/09	AP	
B104 01	12/04/09	DT	R*BLDG FOUNDATION SURVEY VRU #: 001857333
	12/04/09	DA	We need a monolithic slab inspection, that option was not on the list. Thank You 1. Slab must be insulated. 2. Lugs must be squared off and 24 inches wide by plans. 3. Bottom of trenches must be 12 inches below grade at all points. T/S: 12/04/2009 09:50 AM DETAYLOR -----
B104 02	12/07/09	TI	R*BLDG FOUNDATION SURVEY VRU #: 001858299
	12/04/09	CA	We need an inspection for a monolithic slab, that option was not on the list. Thank You T/S: 12/04/2009 02:10 PM NTART -----
B103 01	12/07/09	TI	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001858372
	<u>12/7/09</u>	<u>DP DT</u>	T/S: 12/04/2009 02:10 PM NTART -----

COMMENTS AND NOTES



12/07/2009 10:21:54 AM

Application number, type 09 50023070 CP NEW RESIDENTIAL (SFD)
Property address 580 VALLEY OAK DR

- 1. Lug still not dug in accordance with plans.
 - 2. Bottom of trench at all points must be 12 inches deep.
(Below undisturbed soil)
- \$50 re-inspection fee

T/S: 12/07/2009 10:18 AM DETAYLOR -----



OK Exit Cancel Copy Insert Delete Time stamp User defaults

ADDRESS : 580 VALLEY OAK DR SUBDIV: FOREST OAKS PH 3 99LOTS
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER : WOODSHIRE PARTNERS LLC PHONE :
 PARCEL : 01-0536-05- -0028- -52-
 APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 10/19/2009 11:14 AM RDCONTE ---
 FOREST OAKS PH:3 #165 580 VALLEY OAK
 TAKE 27W, T/L ON NURSERY ROAD. T/L ON
 WOOD POINT DRIVE. T/R ON KIMBROUGH
 DRIVE. T/L ON BLUE OAK. T/L ON VALLEY
 OAK.
 *****SREMC*****

STRUCTURE: 000 000 45X38 SLAB 3BD/2.5BA W/GAR
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	12/02/09 12/02/09	DT AP	R*PLUMB UNDER SLAB VRU #: 001856822
B104 01	12/04/09 12/04/09	DT DA	R*BLDG FOUNDATION SURVEY VRU #: 001857333 We need a monolithic slab inspection, that option was not on the list. Thank You 1. Slab must be insulated. 2. Lugs must be squared off and 24 inches wide by plans. 3. Bottom of trenches must be 12 inches below grade at all points. T/S: 12/04/2009 09:50 AM DETAYLOR -----
B104 02	12/07/09 12/04/09	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001858299 We need an inspection for a monolithic slab, that option was not on the list. Thank You T/S: 12/04/2009 02:10 PM NTART -----
B103 01	12/07/09 12/07/09	DT DP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001858372 T/S: 12/04/2009 02:10 PM NTART ----- 1. Lug still not dug in accordance with plans. 2. Bottom of trench at all points must be 12 inches deep. (Below undisturbed soil) \$50 re-inspection fee T/S: 12/07/2009 10:18 AM DETAYLOR ----- T/S: 12/07/2009 12:05 PM NTART -----
A814 01	12/08/09	TI	ADDRESS CONFIRMATION VRU #: 001858802
B103 02	12/08/09 12/8/09	TI AR DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001858794

COMMENTS AND NOTES

ADDRESS . . : 580 VALLEY OAK DR SUBDIV: FOREST OAKS PH 3 99LOTS
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :
PARCEL . . : 01-0536-05- -0028- -52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/19/2009 11:14 AM RDCONTE ---
FOREST OAKS PH:3 #165 580 VALLEY OAK
TAKE 27W, T/L ON NURSERY ROAD. T/L ON
WOOD POINT DRIVE. T/R ON KIMBROUGH
DRIVE. T/L ON BLUE OAK. T/L ON VALLEY
OAK.
****SREMC****

STRUCTURE: 000 000 45X38 SLAB 3BD/2.5BA W/GAR
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	12/02/09 12/02/09	DT AP	R*PLUMB UNDER SLAB VRU #: 001856822
B104 01	12/04/09 12/04/09	DT DA	R*BLDG FOUNDATION SURVEY VRU #: 001857333 We need a monolithic slab inspection, that option was not on the list. Thank You 1. Slab must be insulated. 2. Lugs must be squared off and 24 inches wide by plans. 3. Bottom of trenches must be 12 inches below grade at all points. T/S: 12/04/2009 09:50 AM DETAYLOR -----
B104 02	12/07/09 12/04/09	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001858299 We need an inspection for a monolithic slab, that option was not on the list. Thank You T/S: 12/04/2009 02:10 PM NTART -----
B103 01	12/07/09 12/07/09	DT DP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001858372 T/S: 12/04/2009 02:10 PM NTART ----- 1. Lug still not dug in accordance with plans. 2. Bottom of trench at all points must be 12 inches deep. (Below undisturbed soil) \$50 re-inspection fee T/S: 12/07/2009 10:18 AM DETAYLOR ----- T/S: 12/07/2009 12:05 PM NTART -----
B103 02	12/08/09 12/08/09	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001858794
A814 01	12/08/09 12/09/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858802 580 valley oak dr lot 165 ----- bunnlevel 28323 T/S: 12/09/2009 03:45 PM TWARD -----
R425 01	12/30/09 <u>12-30</u>	TI <u>DA</u>	FOUR TRADE ROUGH IN VRU #: 001866127

----- COMMENTS AND NOTES -----

ADDRESS : 580 VALLEY OAK DR SUBDIV: FOREST OAKS PH 3 99LOTS
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC PHONE :
PARCEL : 01-0536-05- -0028- -52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/19/2009 11:14 AM RDCONTE ---
FOREST OAKS PH:3 #165 580 VALLEY OAK
TAKE 27W, T/L ON NURSERY ROAD. T/L ON
WOOD POINT DRIVE. T/R ON KIMBROUGH
DRIVE. T/L ON BLUE OAK. T/L ON VALLEY
OAK.
****SREMC****

STRUCTURE: 000 000 45X38 SLAB 3BD/2.5BA W/GAR
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	12/02/09 12/02/09	DT AP	R*PLUMB UNDER SLAB VRU #: 001856822
B104 01	12/04/09 12/04/09	DT DA	R*BLDG FOUNDATION SURVEY VRU #: 001857333 We need a monolithic slab inspection, that option was not on the list. Thank You 1. Slab must be insulated. 2. Lugs must be squared off and 24 inches wide by plans. 3. Bottom of trenches must be 12 inches below grade at all points. T/S: 12/04/2009 09:50 AM DETAYLOR -----
B104 02	12/07/09 12/04/09	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001858299 We need an inspection for a monolithic slab, that option was not on the list. Thank You T/S: 12/04/2009 02:10 PM NTART -----
B103 01	12/07/09 12/07/09	DT DP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001858372 T/S: 12/04/2009 02:10 PM NTART ----- 1. Lug still not dug in accordance with plans. 2. Bottom of trench at all points must be 12 inches deep. (Below undisturbed soil) \$50 re-inspection fee T/S: 12/07/2009 10:18 AM DETAYLOR ----- T/S: 12/07/2009 12:05 PM NTART -----
B103 02	12/08/09 12/08/09	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001858794
A814 01	12/08/09 12/09/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858802 580 valley oak dr lot 165 ----- bunnlevel 28323 T/S: 12/09/2009 03:45 PM TWARD -----
R425 01	12/30/09 12/30/09	KS DA	FOUR TRADE ROUGH IN VRU #: 001866127 1. Master bedroom /bathroom wall shall have double studs when two are bored consecutively. 2. Front porch header over notched and splices do not fall over support posts. 3. upstairs gaurd will not support a 200 pound load

PREPARED 1/05/10, 13:59:05
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 16
DATE 1/06/10

ADDRESS : 580 VALLEY OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-05- -0028- -52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)

SUBDIV: FOREST OAKS PH 3 99LOTS
PHONE : (919) 481-0503
PHONE :

REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

imposed upon it.
OK to side and insulate
T/S: 12/30/2009 11:02 AM KSLATTUM

I129 01 1/06/10 TI R*INSULATION INSPECTION VRU #: 001867705
R425 02 1/06/10 TI FOUR TRADE ROUGH IN VRU #: 001867698

----- COMMENTS AND NOTES -----

ADDRESS . . : 580 VALLEY OAK DR SUBDIV: FOREST OAKS PH 3 99LOTS
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :
PARCEL . . : 01-0536-05- -0028- -52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 10/19/2009 11:14 AM RDCONTE ---
FOREST OAKS PH:3 #165 580 VALLEY OAK
TAKE 27W, T/L ON NURSERY ROAD. T/L ON
WOOD POINT DRIVE. T/R ON KIMBROUGH
DRIVE. T/L ON BLUE OAK. T/L ON VALLEY
OAK.
****SREMC****

STRUCTURE: 000 000 45X38 SLAB 3BD/2.5BA W/GAR
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	12/02/09 12/02/09	DT AP	R*PLUMB UNDER SLAB VRU #: 001856822
B104 01	12/04/09 12/04/09	DT DA	R*BLDG FOUNDATION SURVEY VRU #: 001857333 We need a monolithic slab inspection, that option was not on the list. Thank You 1. Slab must be insulated. 2. Lugs must be squared off and 24 inches wide by plans. 3. Bottom of trenches must be 12 inches below grade at all points. T/S: 12/04/2009 09:50 AM DETAYLOR -----
B104 02	12/07/09 12/04/09	TI CA	R*BLDG FOUNDATION SURVEY VRU #: 001858299 We need an inspection for a monolithic slab, that option was not on the list. Thank You T/S: 12/04/2009 02:10 PM NTART -----
B103 01	12/07/09 12/07/09	DT DP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001858372 T/S: 12/04/2009 02:10 PM NTART ----- 1. Lug still not dug in accordance with plans. 2. Bottom of trench at all points must be 12 inches deep. (Below undisturbed soil) \$50 re-inspection fee T/S: 12/07/2009 10:18 AM DETAYLOR ----- T/S: 12/07/2009 12:05 PM NTART -----
B103 02	12/08/09 12/08/09	DT AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001858794
A814 01	12/08/09 12/09/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001858802 ✓ 580 valley oak dr lot 165 ----- bunnlevel 28323 T/S: 12/09/2009 03:45 PM TWARD -----
R425 01	12/30/09 12/30/09	KS DA	FOUR TRADE ROUGH IN VRU #: 001866127 1. Master bedroom /bathroom wall shall have double studs when two are bored consecutively. 2. Front porch header over notched and splices do not fall over support posts. 3. upstairs gaurd will not support a 200 pound load

ADDRESS : 580 VALLEY OAK DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC
PARCEL : 01-0536-05- -0028- -52-
APPL NUMBER: 09-50023070 CP NEW RESIDENTIAL (SFD)

SUBDIV: FOREST OAKS PH 3 99LOTS
PHONE : (919) 481-0503
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			imposed upon it. OK to side and insulate T/S: 12/30/2009 11:02 AM KSLATTUM
I129 01	1/06/10 1/06/10	DT AP	R*INSULATION INSPECTION VRU #: 001867705
R425 02	1/06/10 1/06/10	DT AP	FOUR TRADE ROUGH IN VRU #: 001867698
H824 01	3/11/10 3/11/10	OT AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001897529 T/S: 03/19/2010 10:17 AM SSTEWARD T/S: 03/19/2010 10:17 AM SSTEWARD
R429 01	5/27/10 <u>5/27/10</u>	TI <u>AP DG</u>	FOUR TRADE FINAL VRU #: 001933215

----- COMMENTS AND NOTES -----

