

-----

ADDRESS . . : 142 BLUEBONNET OAK CT  
 CONTRACTOR : CAVINESS LAND DEVELOPMENT  
 OWNER . . . : WOODSHIRE PARTNERS LLC  
 PARCEL . . . : 01-0536-05- -0028- -70-  
 APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
 142 BLUEBONNET OAK COURT, FOREST OAKS  
 SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
 RD, LEFT ON WOOD POINT DRIVE, RIGHT  
 KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
 ON VALLEY OAK DR, LEFT ON BLUEBONNET  
 OAK COURT, 142 IS ON RIGHT.

-----

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**  
 FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . . : 3.00  
 SEPTIC - EXISTING? . . . . : NEW SEPTIC

PROPOSED USE . . . . . : SFD  
 WATER SUPPLY . . . . . : COUNTY

-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 <u>7/9/10</u>	TI <u>DA DT</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873

----- COMMENTS AND NOTES -----

-----  
ADDRESS . . : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :  
PARCEL . . : 01-0536-05- -0028- -70-  
APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
142 BLUEBONNET OAK COURT, FOREST OAKS  
SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
RD, LEFT ON WOOD POINT DRIVE, RIGHT  
KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
ON VALLEY OAK DR, LEFT ON BLUEBONNET  
OAK COURT, 142 IS ON RIGHT.  
-----

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . : 3.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . . : COUNTY  
-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 7/09/10	DT DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873 1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10 7/12/10	MR CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316 T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10 7/13/10	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390 T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10 <u>7/29/10</u>	TI <u>DA DT</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854

----- COMMENTS AND NOTES -----

ADDRESS . . : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
 OWNER . . : WOODSHIRE PARTNERS LLC PHONE :  
 PARCEL . . : 01-0536-05- -0028- -70-  
 APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
 142 BLUEBONNET OAK COURT, FOREST OAKS  
 SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
 RD, LEFT ON WOOD POINT DRIVE, RIGHT  
 KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
 ON VALLEY OAK DR, LEFT ON BLUEBONNET  
 OAK COURT, 142 IS ON RIGHT.

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**

FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . . : 3.00 PROPOSED USE . . . . . : SFD  
 SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . . : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 7/09/10	DT DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873 1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10 7/12/10	MR CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316 T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10 7/13/10	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390 T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10 7/29/10	DT DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854 1. Entire top of footing shall be free of mortar, dirt, and debris for foundation inspection. Unable to verify projection at several points. Clean off all footers. Where there is not 2 inches solid projection for entire footer depth, have an engineer repair. If repairs are needed, complete them and call for re-inspection T/S: 07/29/2010 11:10 AM DETAYLOR -----
B103 02	7/30/10 <u>7/30/10</u>	TI <u>AP DT</u>	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001961713 T/S: 07/29/2010 01:55 PM JBROCK -----

----- COMMENTS AND NOTES -----

ADDRESS . : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :  
PARCEL . . : 01-0536-05- -0028- -70-  
APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
142 BLUEBONNET OAK COURT, FOREST OAKS  
SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
RD, LEFT ON WOOD POINT DRIVE, RIGHT  
KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
ON VALLEY OAK DR, LEFT ON BLUEBONNET  
OAK COURT, 142 IS ON RIGHT.

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . . : 3.00 PROPOSED USE . . . . . : SFD  
SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . . : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 7/09/10	DT DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873 1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10 7/12/10	MR CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316 T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10 7/13/10	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390 T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10 7/29/10	DT DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854 1. Entire top of footing shall be free of mortar, dirt, and debris for foundation inspection. Unable to verify projection at several points. Clean off all footers. Where there is not 2 inches solid projection for entire footer depth, have an engineer repair. If repairs are needed, complete them and call for re-inspection T/S: 07/29/2010 11:10 AM DETAYLOR -----
B103 02	7/30/10 7/30/10	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001961713 T/S: 07/29/2010 01:55 PM JBROCK -----
B105 01	8/04/10 <u>8/4/10</u>	TI <u>APTD</u>	R*OPEN FLOOR VRU #: 001963423

----- COMMENTS AND NOTES -----

ADDRESS : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
 OWNER : WOODSHIRE PARTNERS LLC PHONE :  
 PARCEL : 01-0536-05- -0028- -70-  
 APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
 142 BLUEBONNET OAK COURT, FOREST OAKS  
 SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
 RD, LEFT ON WOOD POINT DRIVE, RIGHT  
 KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
 ON VALLEY OAK DR, LEFT ON BLUEBONNET  
 OAK COURT, 142 IS ON RIGHT.

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 7/09/10	DT DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873 1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10 7/12/10	MR CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316 T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10 7/13/10	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390 T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10 7/29/10	DT DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854 1. Entire top of footing shall be free of mortar, dirt, and debris for foundation inspection. Unable to verify projection at several points. Clean off all footers. Where there is not 2 inches solid projection for entire footer depth, have an engineer repair. If repairs are needed, complete them and call for re-inspection T/S: 07/29/2010 11:10 AM DETAYLOR -----
B103 02	7/30/10 7/30/10	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001961713 T/S: 07/29/2010 01:55 PM JBROCK -----
B105 01	8/04/10 8/04/10	DT AP	R*OPEN FLOOR VRU #: 001963423
A814 01	8/11/10 8/06/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965145 T/S: 08/06/2010 04:49 PM TWARD ----- 142 BLUEBONNET OAK CT LOT 183 BUNNLEVEL 28323 T/S: 08/06/2010 04:49 PM TWARD -----
R425 01	8/18/10 <u>8/18/10</u>	TI <u>DA DT</u>	FOUR TRADE ROUGH IN VRU #: 001971263

COMMENTS AND NOTES

ADDRESS : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
 OWNER : WOODSHIRE PARTNERS LLC PHONE :  
 PARCEL : 01-0536-05- -0028- -70-  
 APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
 142 BLUEBONNET OAK COURT, FOREST OAKS  
 SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
 RD, LEFT ON WOOD POINT DRIVE, RIGHT  
 KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
 ON VALLEY OAK DR, LEFT ON BLUEBONNET  
 OAK COURT, 142 IS ON RIGHT.

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 7/09/10	DT DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873 1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10 7/12/10	MR CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316 T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10 7/13/10	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390 T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10 7/29/10	DT DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854 1. Entire top of footing shall be free of mortar, dirt, and debris for foundation inspection. Unable to verify projection at several points. Clean off all footers. Where there is not 2 inches solid projection for entire footer depth, have an engineer repair. If repairs are needed, complete them and call for re-inspection T/S: 07/29/2010 11:10 AM DETAYLOR -----
B103 02	7/30/10 7/30/10	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001961713 T/S: 07/29/2010 01:55 PM JBROCK -----
B105 01	8/04/10 8/04/10	DT AP	R*OPEN FLOOR VRU #: 001963423
A814 01	8/11/10 8/06/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965145 T/S: 08/06/2010 04:49 PM TWARD ----- 142 BLUEBONNET OAK CT LOT 183 BUNNLEVEL 28323 T/S: 08/06/2010 04:49 PM TWARD -----
R425 01	8/18/10 8/18/10	DT DA	FOUR TRADE ROUGH IN VRU #: 001971263 1. A1 and A2 trusses next extra hurricane strap at front. 2. Need nail guards for sink water lines in master 3. Caulk kitchen sink water lines. Okay to side and insulate. T/S: 08/18/2010 09:51 AM DETAYLOR -----
I129 01	8/24/10 <u>8/24/10</u>	TI <u>DA</u>	R*INSULATION INSPECTION VRU #: 001974046

CONTINUED ONTO NEXT PAGE

ADDRESS . : 142 BLUEBONNET OAK CT  
CONTRACTOR : CAVINESS LAND DEVELOPMENT  
OWNER . . : WOODSHIRE PARTNERS LLC  
PARCEL . . : 01-0536-05- -0028- -70-  
APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)

SUBDIV: FOREST OAKS PH 3 99LOTS  
PHONE : (919) 481-0503  
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 02	8/24/10 <u>8/24/10</u>	TI <u>DP DT</u>	FOUR TRADE ROUGH IN VRU #: 001974037

----- COMMENTS AND NOTES -----

-----

ADDRESS . . : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
 OWNER . . : WOODSHIRE PARTNERS LLC PHONE :  
 PARCEL . . : 01-0536-05- -0028- -70-  
 APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)

-----

DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
 142 BLUEBONNET OAK COURT, FOREST OAKS  
 SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
 RD, LEFT ON WOOD POINT DRIVE, RIGHT  
 KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
 ON VALLEY OAK DR, LEFT ON BLUEBONNET  
 OAK COURT, 142 IS ON RIGHT.

-----

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**

FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . : 3.00 PROPOSED USE . . . . : SFD  
 SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . : COUNTY

-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873
	7/09/10	DA	1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316
	7/12/10	CA	T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390
	7/13/10	AP	T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854
	7/29/10	DA	1. Entire top of footing shall be free of mortar, dirt, and debris for foundation inspection. Unable to verify projection at several points. Clean off all footers. Where there is not 2 inches solid projection for entire footer depth, have an engineer repair. If repairs are needed, complete them and call for re-inspection T/S: 07/29/2010 11:10 AM DETAYLOR -----
B103 02	7/30/10	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001961713
	7/30/10	AP	T/S: 07/29/2010 01:55 PM JBROCK -----
B105 01	8/04/10	DT	R*OPEN FLOOR VRU #: 001963423
	8/04/10	AP	
A814 01	8/11/10	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965145
	8/06/10	AP	T/S: 08/06/2010 04:49 PM TWARD ----- 142 BLUEBONNET OAK CT LOT 183 BUNNLEVEL 28323 T/S: 08/06/2010 04:49 PM TWARD -----
R425 01	8/18/10	DT	FOUR TRADE ROUGH IN VRU #: 001971263
	8/18/10	DA	1. A1 and A2 trusses next extra hurricane strap at front. 2. Need nail guards for sink water lines in master 3. Caulk kitchen sink water lines. Okay to side and insulate. T/S: 08/18/2010 09:51 AM DETAYLOR -----
I129 01	8/24/10	DT	R*INSULATION INSPECTION VRU #: 001974046



-----  
ADDRESS . . : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :  
PARCEL . . : 01-0536-05- -0028- -70-  
APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
-----

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 02	8/24/10 8/24/10 8/24/10	DA BT DP	FOUR TRADE ROUGH IN VRU #: 001974037 Previous violations 1 and 2 still not corrected \$50.00 re-inspection fee T/S: 08/24/2010 10:22 AM DETAYLOR -----
I129 02	8/25/10 <u>8/25/10</u>	TI AP DJ	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001974724 T/S: 08/24/2010 02:20 PM NTART -----
R425 03	8/25/10 <u>8/25/10</u>	TI AP DJ	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001974716 T/S: 08/24/2010 02:05 PM NTART -----

----- COMMENTS AND NOTES -----  
-----

ADDRESS : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
 OWNER : WOODSHIRE PARTNERS LLC PHONE :  
 PARCEL : 01-0536-05- -0028- -70-  
 APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
 142 BLUEBONNET OAK COURT, FOREST OAKS  
 SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
 RD, LEFT ON WOOD POINT DRIVE, RIGHT  
 KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
 ON VALLEY OAK DR, LEFT ON BLUEBONNET  
 OAK COURT, 142 IS ON RIGHT.

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 7/09/10	DT DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873 1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10 7/12/10	MR CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316 T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10 7/13/10	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390 T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10 7/29/10	DT DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854 1. Entire top of footing shall be free of mortar, dirt, and debris for foundation inspection. Unable to verify projection at several points. Clean off all footers. Where there is not 2 inches solid projection for entire footer depth, have an engineer repair. If repairs are needed, complete them and call for re-inspection T/S: 07/29/2010 11:10 AM DETAYLOR -----
B103 02	7/30/10 7/30/10	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001961713 T/S: 07/29/2010 01:55 PM JBROCK -----
B105 01	8/04/10 8/04/10	DT AP	R*OPEN FLOOR VRU #: 001963423
A814 01	8/11/10 8/06/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965145 T/S: 08/06/2010 04:49 PM TWARD ----- ✓ 142 BLUEBONNET OAK CT LOT 183 BUNNLEVEL 28323 T/S: 08/06/2010 04:49 PM TWARD -----
R425 01	8/18/10 8/18/10	DT DA	FOUR TRADE ROUGH IN VRU #: 001971263 1. A1 and A2 trusses next extra hurricane strap at front. 2. Need nail guards for sink water lines in master 3. Caulk kitchen sink water lines. Okay to side and insulate. T/S: 08/18/2010 09:51 AM DETAYLOR -----
I129 01	8/24/10 8/24/10	DT DA	R*INSULATION INSPECTION VRU #: 001974046

-----  
ADDRESS . : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
OWNER . . : WOODSHIRE PARTNERS LLC PHONE :  
PARCEL . . : 01-0536-05- -0028- -70-  
APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
-----

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 02	8/24/10 8/24/10	DT DP	FOUR TRADE ROUGH IN VRU #: 001974037 Previous violations 1 and 2 still not corrected \$50.00 re-inspection fee T/S: 08/24/2010 10:22 AM DETAYLOR -----
I129 02	8/25/10 8/25/10	DT AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001974724 T/S: 08/24/2010 02:20 PM NTART -----
R425 03	8/25/10 8/25/10	DT AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001974716 T/S: 08/24/2010 02:05 PM NTART -----
H824 01	9/22/10 9/22/10	OT DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001985951 WATER LINE TO BE CHECKED. T/S: 09/22/2010 01:34 PM SZIMMER ----- T/S: 09/22/2010 01:35 PM SZIMMER -----
H824 02	10/12/10 10/12/10	OT AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994045 T/S: 10/13/2010 10:26 AM SZIMMER ----- T/S: 10/13/2010 10:26 AM SZIMMER -----
R429 01	11/23/10	TI	FOUR TRADE FINAL VRU #: 002010344

11-23-10 DP-MR

----- COMMENTS AND NOTES -----

-----

ADDRESS . . : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
 OWNER . . . : WOODSHIRE PARTNERS LLC PHONE :  
 PARCEL . . . : 01-0536-05- -0028- -70-  
 APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 03/31/2010 09:30 AM VBROWN ----  
 142 BLUEBONNET OAK COURT, FOREST OAKS  
 SUB DIV #183 PH3. 27W, LEFT ON NURSERY  
 RD, LEFT ON WOOD POINT DRIVE, RIGHT  
 KIMBROUGH DR, LEFT ON BLUE OAK DR, LEFT  
 ON VALLEY OAK DR, LEFT ON BLUEBONNET  
 OAK COURT, 142 IS ON RIGHT.

-----

**STRUCTURE: 000 000 40X47 3BDR 2.5BATH SFD WITH GAR SLAB**

FLOOD ZONE . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . . : 3.00 PROPOSED USE . . . . . : SFD  
 SEPTIC - EXISTING? . . . . : NEW SEPTIC WATER SUPPLY . . . . . : COUNTY

-----

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/09/10 7/09/10	DT DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001951873 1. Lugs at side of garage doors not dug to plan specs. 2. Plans do not have slab foundation page.. T/S: 07/09/2010 10:23 AM DETAYLOR -----
B101 02	7/12/10 7/12/10	MR CA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001952316 T/S: 07/09/2010 10:55 AM VBROWN ----- T/S: 07/12/2010 12:43 PM MREARIC -----
B101 03	7/13/10 7/13/10	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001953390 T/S: 07/13/2010 01:34 PM MREARIC -----
B103 01	7/29/10 7/29/10	DT DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001960854 1. Entire top of footing shall be free of mortar, dirt, and debris for foundation inspection. Unable to verify projection at several points. Clean off all footers. Where there is not 2 inches solid projection for entire footer depth, have an engineer repair. If repairs are needed, complete them and call for re-inspection T/S: 07/29/2010 11:10 AM DETAYLOR -----
B103 02	7/30/10 7/30/10	DT AP	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001961713 T/S: 07/29/2010 01:55 PM JBROCK -----
B105 01	8/04/10 8/04/10	DT AP	R*OPEN FLOOR VRU #: 001963423
A814 01	8/11/10 8/06/10	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001965145 T/S: 08/06/2010 04:49 PM TWARD ----- 142 BLUEBONNET OAK CT LOT 183 BUNNLEVEL 28323 T/S: 08/06/2010 04:49 PM TWARD -----
R425 01	8/18/10 8/18/10	DT DA	FOUR TRADE ROUGH IN VRU #: 001971263 1. A1 and A2 trusses next extra hurricane strap at front. 2. Need nail guards for sink water lines in master 3. Caulk kitchen sink water lines. Okay to side and insulate. T/S: 08/18/2010 09:51 AM DETAYLOR -----
I129 01	8/24/10 8/24/10	DT DA	R*INSULATION INSPECTION VRU #: 001974046

----- CONTINUED ONTO NEXT PAGE -----

ADDRESS : 142 BLUEBONNET OAK CT SUBDIV: FOREST OAKS PH 3 99LOTS  
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503  
OWNER : WOODSHIRE PARTNERS LLC PHONE :  
PARCEL : 01-0536-05- -0028- -70-  
APPL NUMBER: 10-50024081 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R425 02	8/24/10 8/24/10	DT DP	FOUR TRADE ROUGH IN VRU #: 001974037 Previous violations 1 and 2 still not corrected \$50.00 re-inspection fee T/S: 08/24/2010 10:22 AM DETAYLOR -----
I129 02	8/25/10 8/25/10	DT AP	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001974724 T/S: 08/24/2010 02:20 PM NTART -----
R425 03	8/25/10 8/25/10	DT AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001974716 T/S: 08/24/2010 02:05 PM NTART -----
H824 01	9/22/10 9/22/10	OT DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001985951 WATER LINE TO BE CHECKED. T/S: 09/22/2010 01:34 PM SZIMMER ----- T/S: 09/22/2010 01:35 PM SZIMMER -----
H824 02	10/12/10 10/12/10	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994045 T/S: 10/13/2010 10:26 AM SZIMMER ----- T/S: 10/13/2010 10:26 AM SZIMMER -----
R429 01	11/23/10 11/23/10	MR DP	FOUR TRADE FINAL VRU #: 002010344 T/S: 11/23/2010 09:19 AM MREARIC ----- ac in attic is not wired no light or recept in attic
R429 02	11/24/10 <u>11/24/10</u>	TI <u>AP DT</u>	FOUR TRADE FINAL VRU #: 002011393

----- COMMENTS AND NOTES -----

County of Harnett  
Building Inspections Department  
Planning Services

**Certificate of Compliance: \_\_\_ Occupancy: X**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

**Permit Numbers**

Name: Caviness Land Development

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Address: 142 Bluebonnet Oak Ct  
Bunnlevel, NC 28323

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: 1050024081

MFG Home: \_\_\_\_\_

Date: 11/24/10

Building Official: [Signature]