## **County of Harnett Building Inspections Department Planning Services** Certificate of Compliance: \_\_\_ Occupancy: \_\_\_ Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following: Use Classification: SEII **Permit Numbers** Name: Savuy Domes Building:\_\_\_\_ Electrical: Address: 65 EMMg (+ Insulation: Plumbing: Mechanical: MFG Home: **Building Official:** Date: 1-24-12

Harnett County

INSPECTION TICKET

INSPECTOR: IVR

PAGE

DATE 1/24/12

ADDRESS . : 65 EMMA CT SUBDIV: KENLAN FARMS PH1 SET1 41LOTS

CONTRACTOR : PHONE : OWNER . . : ABJ INVESTMENTS LLC PHONE :

PARCEL . . : 12-0555- - -0216- -05-

APPL NUMBER: 10-50025066 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: T/S: 08/19/2010 10:08 AM VBROWN ---65 EMMA COURT, KENLAN FARMS #5. 401S,
RIGHT ON MCNEILL HOBBS RD, LEFT ON
WIRE RD, PASS JOSEY WILLIAMS RD ON THE

LEFT AND TURN RIGHT ON KENLAN RD.

-----

STRUCTURE: 000 000 43.4X56.5 4BDR 2.5BATH SFD W GAR, MONO

FLOOD ZONE . . . : FLOOD ZONE X

# BEDROOMS . . . . . : 4.00 PROPOSED USE . . . . . : SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . . : COUNTY

YP/SQ	REQUESTED COMPLETED		DESCRIPTION RESULTS/COMMENTS
814 01	11/14/11	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002160372
	11/17/11	AP	65 EMMA CT LOT 5 LINDEN 28356
			T/S: 11/17/2011 12:21 PM TWARD
3114 01	11/15/11	JH	R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 0021603
	11/15/11	CA	Per DEREK
P309 01	11/15/11	JH	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002160398
	11/15/11	AP	T-Pole Passed
B114 02	11/17/11	DT	R*BLDG MONO SLAB/TEMP SVC POLE VRU #: 002161651
	11/17/11	AP	
2427 01	12/12/11	JH	FOUR TRADE ROUGH IN >2500 VRU #: 002170587
	12/12/11	CA	PER ANDREW
427 02	12/13/11	JH	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002171692
	12/13/11	DA	1) Missing anchor bolts throughout house. 2) Add 2 studs on
			each side of garage header per plans. 3) Add stud to right
			of door in garage. 4) Missing nail guard on 3" pipe to right
			of door in garage @ bottom plate. 5) Need 2 studs under
			double I joist to the right of refrig. 6) Missing point load
			in family room & hall @ half bath.
427 03	12/14/11	JH	FOUR TRADE ROUGH IN >2500 VRU #: 002172039
	12/14/11	AP	
I129 01	12/20/11	JH	R*INSULATION INSPECTION VRU #: 002174563
	12/20/11	AP	
H824 01		вм	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002182681
	1/17/12	AP	T/S: 01/18/2012 11:23 AM SZIMMER
			T/S: 01/18/2012 11:24 AM SZIMMER
M305 01	1/18/12	JH	R*PLUMB SEWER CONNECTION VRU #: 002182368
	1/18/12	CA	PER CARSON
1305 02	1/19/12	JH	R*PLUMB SEWER CONNECTION VRU #: 002183069
	1/19/12	AP	
R431 01	1/23/12	JH	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 002184257
	1/23/12	DA	1) Handrails in stairway needs to be continuous. 2) Seal
		200 S. 400 N	refrigerant lines @ AHUs in attic.
R431 02	1/24/12	TI .	FOUR TRADE FINAL >2500 VRU #: 002184869
	1-70-12	ADTH	
	10410	++ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	

----- COMMENTS AND NOTES -----