## **County of Harnett Building Inspections Department Planning Services** Certificate of Compliance: Occupancy: X Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following: Use Classification: Residential **Permit Numbers** Name: Savry Homes, LLC Building: Electrical: Insulation: Plumbing: 50 Address: 300 Emma Ct Linden NK 28356 Mechanical: \ MFG Home: Building Official: Date: 11/5/12

PREPARED 11/05/12, 7:34:50 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 11/05/12

\_\_\_\_\_\_ ADDRESS . : 300 EMMA CT SUBDIV: KENLAN FARMS PH1 SET1 41LOTS

CONTRACTOR : SAVVY HOMES, LLC PHONE: (919) 781-8104 OWNER . . : SAVVY HOMES LLC PHONE: (919) 800-7419

PARCEL . . : 12-0555- - -0216- -20-

APPL NUMBER: 12-50028607 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 03/22/2012 10:55 AM JBROCK ----

FROM LILLINGTON TAKE HWY 210 TOWARDS FAYE TAKE LEFT AT MCNEILL HOBBS RD FOLLOW FOR ABOUT 4.5 MILES TO TURN R AT WIRE RD KENLAN FARMS S/D IS LOCATED APPROX 3.5 MILES ON THE RIGHT LOT 20

\_\_\_\_\_\_

## STRUCTURE: 000 000 56.5X43.4 4BDR SLAB W/ GARAGE & PATIO

FLOOD ZONE . . . : FLOOD ZONE X

9/24/12

DA

# BEDROOMS . . . PROPOSED USE . . . . . . : SFD . . . . . : 4000000.00

SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . . . : COUNTY \_\_\_\_\_\_ PERMIT: CPSF 00 CP \* SFD REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ------A814 01 7/26/12 TW ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002257533 7/27/12 AP 300 EMMA CT LOT 20 LINDEN 28356-----T/S: 07/27/2012 12:54 PM TWARD ------B101 01 7/26/12 R\*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002257525 JH JH DA 7/26/12 Need soil letter for engineer fill in footing--T-POLE PASSED JH · R\*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002258093 B101 02 7/27/12 AP 7/27/12 T/S: 07/26/2012 01:58 PM VBROWN ------B103 01 8/06/12 JH R\*BLDG FOUND & TEMP SVC POLE VRU #: 002261170 Missing insulation on foundation wall per code. 8/06/12 DA T/S: 08/06/2012 01:53 PM JHALL -----B103 02 8/07/12 JH R\*BLDG FOUND & TEMP SVC POLE VRU #: 002261782 8/07/12 DP Insulation for foundation per code is R10 - 2".-----B103 03 8/08/12 JH R\*BLDG FOUND & TEMP SVC POLE VRU #: 002262350 8/08/12 CA PER BRAD B103 04 8/09/12 JH R\*BLDG FOUND & TEMP SVC POLE VRU #: 002262970 8/09/12 AP R\*PLUMB UNDER SLAB VRU #: 002264976 P309 01 8/14/12 JΗ 8/14/12 Need 10' head of water on drain lines under slab plumbing. DA 8/15/12 R\*PLUMB UNDER SLAB VRU #: 002265734 P309 02 JH 8/15/12 8/17/12 AP B111 01 R\*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002266898 DT8/17/12 AΡ 9/21/12 FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002281269 R425 01 JΗ 9/21/12 CA T/S: 09/20/2012 11:03 AM VBROWN ------PER ANDREW JH R425 02 FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002282184 9/24/12

> showers.4) Missing jack studs on right side of window in dining room per plans.5) Missing HTT5 anchors per plans on back wall & on garage wall.6) Missing S3A page for

garage.2) Need air barriers in garage between I joist on garage wall & seal per code.3) Fire aculk under all tubs &

1) Need 4 studs under each end of girder truss in

PREPARED 11/05/12, 7:34:50 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 11/05/12

------ADDRESS . : 300 EMMA CT

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS

CONTRACTOR : SAVVY HOMES, LLC OWNER . . : SAVVY HOMES LLC

PHONE : (919) 781-8104 PHONE: (919) 800-7419

PARCEL . . : 12-0555- - -0216- -20-

APPL NUMBER: 12-50028607 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			plans.7)Missing stud over door in bed4.8)Block & seal front
			wall in master bed closet for air barriers.9) Fire caulk
P425 03	9/27/12	JH	holes in master bath top plate @ sinks.
1425 05	9/27/12	DP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002283828
	J/ Z// 12	DF .	T/S: 09/26/2012 12:08 PM DJOHNSON
	•		PAY \$50 RE FEE
R425 04	9/28/12	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002284354
	9/28/12	AP	
I129 01	10/03/12	JН	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002285781
	10/03/12	AP	T/S: 10/02/2012 08:54 AM VBROWN
H824 01	10/17/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002292720
	10/17/12	AP	T/S: 10/18/2012 09:07 AM SSTEWART
			T/S: 10/18/2012 09:07 AM SSTEWART
R429 01	10/31/12	DT	FOUR TRADE FINAL TIME: 17:00 VRU #: 002297760
	10/31/12	CA	T/S: 10/31/2012 11:06 AM DETAYLOR
			Per Josh
8429 02	, . ,	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 002298131
	11/01/12	DA	1) Missing fall protection devices on windows upstairs per
	l		code.2)Seal refrigerant lines @ AHU.3)Fill joints in blocks
			on left side of garage oiutside.4) Sewer cleanout needs to
•			be down to garde level.5)Missing treated wood under threshold @ back door.
429 03	11/05/12	тт	
.127 03	11/5/12	ACM	FOUR TRADE FINAL TIME: 17:00 VRU #: 002299352
	1112/16	HO W	