

ADDRESS : 459 FIFTY CALIBER DR
 CONTRACTOR : BILL CLARK HOMES LLC
 OWNER : BILL CLARK HOMES OF FAYET
 PARCEL : 03-9597- - -0039- -19-
 APPL NUMBER: 12-50029074 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/06/2012 08:46 AM JBROCK ----
 27 TOWARDS 87 TURN LEFT ON TINGEN RD
 TURN LEFT INTO S/D ON STRIKE EAGLE DR
 TURN LEFT ON BUNKER BUSTER & LEFT ON
 FIFTY CALIBER DR LOT ON LEFT LOT 22

STRUCTURE: 000 000 52X30 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00
 SEPTIC - EXISTING? : NEW TANK
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/29/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002245706
	6/29/12	AP	T/S: 06/29/2012 11:09 AM MREARIC -----
B103 01	7/11/12	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 002250316
	7/11/12	AP	T/S: 07/11/2012 12:26 PM MREARIC -----
B111 01	7/13/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002251360
	7/13/12	DA	T/S: 07/13/2012 11:44 AM MREARIC ----- not ready
A814 01	7/17/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002252740
	7/19/12	AP	T/S: 07/16/2012 12:33 PM DJOHNSON ----- 459 FIFTY CALIBER DR LOT 22 BROADWAY 27505----- T/S: 07/19/2012 03:15 PM TWARD -----
P309 01	7/17/12	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002252898
	7/17/12	AP	T/S: 07/16/2012 02:13 PM DJOHNSON ----- CUSTOMER ASKED FOR PLUMBING UNDER SLAB. WAS NOT SURE IF THIS WAS WHAT WAS NEEDED. COULD NOT GET UP WITH PAUL... T/S: 07/17/2012 11:25 AM DETAYLOR -----
B111 02	7/19/12	FS	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002253888
	7/19/12	AP	T/S: 07/18/2012 10:56 AM VBROWN ----- T/S: 07/19/2012 03:35 PM FSPIVEY -----
R425 01	8/13/12	DT	FOUR TRADE ROUGH IN VRU #: 002264294
	8/13/12	DA	T/S: 08/13/2012 10:31 AM DETAYLOR ----- No truss documents Need engineer repair where truss above bottom of stairs is bored for low voltage wiring Need 30 inch vertical clearance over attic platform and catwalk Okay to side, do not insulate
R425 02	8/15/12	DT	FOUR TRADE ROUGH IN VRU #: 002265426
	8/15/12	DA	T/S: 08/15/2012 03:20 PM DJOHNSON -----
R425 03	8/17/12	FS	FOUR TRADE ROUGH IN VRU #: 002267460
	8/17/12	CA	
R425 04	8/20/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002268076
	8/20/12	DA	T/S: 08/20/2012 02:23 PM MREARIC ----- attic accessclearanceto be 30"
I129 01	8/22/12	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002268993
	8/22/12	AP	T/S: 08/22/2012 01:44 PM MREARIC -----

PREPARED: 10/15/12, 13:57:16
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 8
DATE 10/16/12

ADDRESS . . : 459 FIFTY CALIBER DR
CONTRACTOR : BILL CLARK HOMES LLC
OWNER . . . : BILL CLARK HOMES OF FAYET
PARCEL . . . : 03-9597- - -0039- -19-
APPL NUMBER: 12-50029074 CP NEW RESIDENTIAL (SFD)

SUBDIV: PATTONS POINT
PHONE : (252) 355-5805
PHONE : (910) 263-9026

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R125 01	8/22/12	MR	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002269009
	8/22/12	AP	T/S: 08/22/2012 01:44 PM MREARIC ----- reviewed truss info
H824 01	8/23/12	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002270767
	8/23/12	AP	✓ T/S: 08/24/2012 12:43 PM SSTEWARD ----- T/S: 08/24/2012 12:44 PM SSTEWARD -----
R429 01	10/16/12	TI	FOUR TRADE FINAL VRU #: 002291326
	<u>10-16-12</u>	<u>DP-MR</u>	

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DATE: 10/16/2012

PERMIT # 12-50029074

ADDRESS: 459 fifty caliper

- 1. The steps to garage are missing**
- 2. The numbers are falling off house**
- 3. The attic access hole must be weather-stripped**
- 4. The access door must also be insulated R-10**
- 5. The energy certificate must be permanently affixed to house either at the panel ,attic access area, or the kitchen cabinets**
- 6. Fee 50**

Mike Rearic cell# (910) 984- 4772

ADDRESS . . : 459 FIFTY CALIBER DR SUBDIV: PATTONS POINT
 CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805
 OWNER . . . : BILL CLARK HOMES OF FAYET PHONE : (910) 263-9026
 PARCEL . . . : 03-9597- - -0039- -19-
 APPL NUMBER: 12-50029074 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 06/06/2012 08:46 AM JBROCK ----
 27 TOWARDS 87 TURN LEFT ON TINGEN RD
 TURN LEFT INTO S/D ON STRIKE EAGLE DR
 TURN LEFT ON BUNKER BUSTER & LEFT ON
 FIFTY CALIBER DR LOT ON LEFT LOT 22

STRUCTURE: 000 000 52X30 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/29/12	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002245706
	6/29/12	AP	T/S: 06/29/2012 11:09 AM MREARIC -----
B103 01	7/11/12	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 002250316
	7/11/12	AP	T/S: 07/11/2012 12:26 PM MREARIC -----
B111 01	7/13/12	MR	R*BLDG SLAB INSP/TEMP SVC POLE VRU #: 002251360
	7/13/12	DA	T/S: 07/13/2012 11:44 AM MREARIC ----- not ready
A814 01	7/17/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002252740
	7/19/12	AP	T/S: 07/16/2012 12:33 PM DJOHNSON ----- ✓ 459 FIFTY CALIBER DR LOT 22 BROADWAY 27505---- T/S: 07/19/2012 03:15 PM TWARD -----
P309 01	7/17/12	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002252898
	7/17/12	AP	T/S: 07/16/2012 02:13 PM DJOHNSON ----- CUSTOMER ASKED FOR PLUMBING UNDER SLAB. WAS NOT SURE IF THIS WAS WHAT WAS NEEDED. COULD NOT GET UP WITH PAUL... T/S: 07/17/2012 11:25 AM DETAYLOR -----
B111 02	7/19/12	FS	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002253888
	7/19/12	AP	T/S: 07/18/2012 10:56 AM VBROWN ----- T/S: 07/19/2012 03:35 PM FSPIVEY -----
R425 01	8/13/12	DT	FOUR TRADE ROUGH IN VRU #: 002264294
	8/13/12	DA	T/S: 08/13/2012 10:31 AM DETAYLOR ----- No truss documents Need engineer repair where truss above bottom of stairs is bored for low voltage wiring Need 30 inch vertical clearance over attic platform and catwalk Okay to side, do not insulate
R425 02	8/15/12	DT	FOUR TRADE ROUGH IN VRU #: 002265426
	8/15/12	DA	T/S: 08/15/2012 03:20 PM DJOHNSON -----
R425 03	8/17/12	FS	FOUR TRADE ROUGH IN VRU #: 002267460
	8/17/12	CA	
R425 04	8/20/12	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002268076
	8/20/12	DA	T/S: 08/20/2012 02:23 PM MREARIC ----- attic accessclearanceto be 30"
I129 01	8/22/12	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002268993
	8/22/12	AP	T/S: 08/22/2012 01:44 PM MREARIC -----

ADDRESS . . : 459 FIFTY CALIBER DR SUBDIV: PATTONS POINT
CONTRACTOR : BILL CLARK HOMES LLC PHONE : (252) 355-5805
OWNER . . : BILL CLARK HOMES OF FAYET PHONE : (910) 263-9026
PARCEL . . : 03-9597- - -0039- -19-
APPL NUMBER: 12-50029074 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R125 01	8/22/12	MR	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002269009
	8/22/12	AP	T/S: 08/22/2012 01:44 PM MREARIC ----- reviewed truss info
H824 01	8/23/12	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002270767
	8/23/12	AP	T/S: 08/24/2012 12:43 PM SSTEWARD ----- T/S: 08/24/2012 12:44 PM SSTEWARD -----
R429 01	10/16/12	MR	FOUR TRADE FINAL VRU #: 002291326
	10/16/12	DP	T/S: 10/16/2012 09:33 AM MREARIC ----- 1. no garage steps 2. numbers falling off house 3. attic access must be weather-stripped 4. access door must be insulatede R-10, 5. post energy cert in proper place
R429 02	10/22/12	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002293579
	<u>10-22-12</u>	<u>CA-MR</u>	T/S: 10/19/2012 12:20 PM VBROWN -----

----- COMMENTS AND NOTES -----

Per Paul 8:31