

ADDRESS : 14 KENLAN RD SUBDIV: KENLAN FARMS PH1 SET1 41LOTS
 CONTRACTOR : SAVVY HOMES, LLC PHONE : (919) 781-8104
 OWNER : ABJ INVESTMENTS LLC PHONE :
 PARCEL : 12-0555- - -0216- -41-
 APPL NUMBER: 12-50029525 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 08/08/2012 10:20 AM JBROCK ----
 FROM LILLINGTON TAKE HWY 210 TOWARDS
 FAYETTEVILLE TAKE LEFT AT MCNEILL HOBBS
 RD FOLLOW FOR ABOUT 4.5 MILES TO TURN R
 AT WIRE RD KENKLAN FARMS S/D LOCATED
 APPROX 3.5 MILES ON THE R LOT 77

STRUCTURE: 000 000 42.4X51 4BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	9/25/12	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002282747
	9/25/12	AP	T/S: 09/25/2012 10:37 AM DETAYLOR -----
A814 01	10/11/12	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002289627
	10/16/12	AP	14 KENLAN RD LOT 77 LINDEN 28356----- T/S: 10/16/2012 03:25 PM TWARD -----
B103 01	10/11/12	JH	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002289619
	10/11/12	CA	PER BRIAN -----
B103 02	10/12/12	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 002290328
	10/12/12	AP	T/S: 10/12/2012 03:00 PM MREARIC -----
P309 01	10/19/12	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002292902
	10/19/12	AP	T/S: 10/18/2012 11:25 AM VBROWN ----- T/S: 10/19/2012 01:20 PM DETAYLOR -----
B111 01	10/25/12	JH	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002295699
	10/25/12	AP	-----
R425 01	12/20/12	JH	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002318582
	12/20/12	DA	1)Missing roof boots.2)Add 1 jack on each end header in study room.3)Nail all 2 & 3 ply roof trussess per truss drawings.4)C01 truss missing bracing.5)10psi on gas line.6)Missing receptacle on front of house accessible from grade.
R425 02	12/31/12	JH	FOUR TRADE ROUGH IN VRU #: 002321453
	12/31/12	AP	-----
H824 01	1/07/13	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002324788
	1/07/13	AP	T/S: 01/08/2013 11:09 AM SSTEWARD ----- T/S: 01/08/2013 11:10 AM SSTEWARD -----
I129 01	1/08/13	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002324531
	1/08/13	DA	1)Missing insulation in Ts in garage.2)Missing insulation around doors & windows.3)Top & bottom plates not sealed per code.
I129 02	1/11/13	DT	R*INSULATION INSPECTION VRU #: 002325801
	1/11/13	AP	T/S: 01/11/2013 11:24 AM DETAYLOR -----
M305 01	1/18/13	JH	R*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 002328391
	1/18/13	AP	-----
R429 01	2/11/13	TI	FOUR TRADE FINAL VRU #: 002337350

2-11-13 OAJH