

ADDRESS : 50 ISON LN
CONTRACTOR : GARY ROBINSON HOMES LLC
OWNER : JJJB INVESTMENTS, LLC
PARCEL : 11-0651- - -0057- -60-
APPL NUMBER: 15-50035354 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : T/S: 01/16/2015 02:42 PM JBROCK ----
HWY 210 N FROM LILLINGTON TURN L ONTO
TRIPP RD L ONTO SCUPERNANG SECOND - R
AT END OF CUL-DE-SAC LOT 25
T/S: 02/19/2015 10:40 AM VBROWN ----
premis number 86564778
LOCK BOX #:5383

SUBDIV: PLTN VINEYARD GREEN
PHONE : (910) 977-2562
PHONE :

LAND NOTES : LXMN 10/05/04 SPLIT FROM THE 04 PARCEL

STRUCTURE: 000 000 43X40 3BDR SLAB W/ GARAGE

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3000000.00
SEPTIC - EXISTING? : NEW TANK
PROPOSED USE : SFD
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/03/15	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002630166 T/S: March 03, 2015 03:05 PM BSUTTON
A814 01	3/12/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002633808 50 ISON LN LILLINGTON 27546 POST # ON HOME T/S: 03/12/2015 09:30 AM SBENNETT
B103 01	3/12/15	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002633790 T/S: 03/11/2015 12:45 PM VBROWN T/S: 03/12/2015 03:20 PM DETAYLOR
P309 01	3/18/15	BS	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002636256 T/S: March 18, 2015 03:24 PM BSUTTON
B111 01	3/23/15	BS	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002637528 T/S: 03/20/2015 12:57 PM DJOHNSON ASKED FOR STEM WALL SLAB INSPECTION T/S: March 23, 2015 03:15 PM BSUTTON Verified all three interior lug footings
B104 01	4/15/15	DJ	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002647105 T/S: 04/15/2015 08:01 AM DJOHNSON T/S: 04/15/2015 08:01 AM DJOHNSON
R425 01	4/15/15	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002647113 T/S: 04/15/2015 08:01 AM DJOHNSON T/S: April 15, 2015 11:04 AM BSUTTON Brace truss M1 at tply. 2. Brace truss A1 on front side at center of web, and at ceiling as shown on truss documents. Need jack studs under LVL at kitchen end above window.4. Install 2' CS 16 strap between master bedroom window and corner. Ok to side/insulate.
I129 01	4/17/15	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002647659 T/S: 04/16/2015 09:43 AM LBENNETT T/S: April 17, 2015 02:49 PM BSUTTON
R425 02	4/17/15	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002647667 T/S: 04/16/2015 09:43 AM LBENNETT T/S: April 17, 2015 02:49 PM BSUTTON

CONTINUED ONTO NEXT PAGE

 ADDRESS : 50 ISON LN
 CONTRACTOR : GARY ROBINSON HOMES LLC
 OWNER : JJJB INVESTMENTS, LLC
 PARCEL : 11-0651- - -0057- -60-
 APPL NUMBER: 15-50035354 CP NEW RESIDENTIAL (SFD)
 SUBDIV: PLTN VINEYARD GREEN
 PHONE : (910) 977-2562
 PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	6/03/15 6/03/15	JM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002667624 PER JAMES MANHART OPERATIONS PERMIT ON HOLD, NEEDS COVER, PUMP AND ALARM TO BE CHECKED BEFORE PERMIT CAN BE ISSUED. CALL HIM 893-7547 WHEN READY. T/S: 06/03/2015 08:35 AM S STEWART -----
E209 01	6/23/15 6/23/15	MR DA	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002677953 T/S: 06/22/2015 01:08 PM LBENNETT ----- T/S: 06/23/2015 01:31 PM MREARIC ----- secure the range outlet poer code
E209 02	6/25/15 6/25/15	BS AP	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002678894 T/S: 06/24/2015 10:11 AM LBENNETT ----- Previous violation corrected. BSUTTON -----
H824 02	7/01/15 7/01/15	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002683068 T/S: 07/02/2015 11:14 AM S STEWART ----- T/S: 07/02/2015 11:15 AM S STEWART -----
R429 01	7/20/15 7/20/15	BS DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002690634 T/S: 07/17/2015 01:43 PM LBENNETT ----- T/S: July 20, 2015 02:52 PM BSUTTON ----- Doors locked.No lock box code on paperwork. Repair vinyl siding at right side near AC unit
R429 02	7/22/15 7/22/15	BS DP	FOUR TRADE FINAL TIME: 17:00 VRU #: 002691616 T/S: 07/21/2015 08:27 AM LBENNETT ----- LOCKOX CODE: 5383 T/S: July 22, 2015 02:14 PM BSUTTON ----- Weatherstrip and insulate attic access door in bedroom ceiling. Foam seal around attic access doors in kneewall. Repair vinyl siding on right side of house as previously written up.
R429 03	7/28/15 <u>7/28/15</u>	TI <u>AB</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002694636 T/S: 07/27/2015 01:23 PM LBENNETT ----- LOCKBOX CODE- 5383

----- COMMENTS AND NOTES -----

Lot 1
15-50036452
72365725
35

15-5-36453
14627828

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: SFD

Name: Gary Robinson Homes LLC

Address: 50 Ison Lane

Lillington, N.C. 27546

Date: 7-28-2015

Building Official: B. B. [Signature]

Permit Numbers

Building: 15-50035354

Electrical: " "

Insulation: " "

Plumbing: " "

Mechanical: " "

~~MFG Home~~

