

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Buchanan Roofing Inc

Address: 121 Starlight

Date: 4/29/16

Permit Numbers

Building: _____

Electrical: _____


Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

Building Official: _____



50036199

ADDRESS . . : 121 STARLIGHT DR SUBDIV: NEW HORIZONS
 CONTRACTOR : PHONE :
 OWNER . . . : BUCHANAN ROOFING INC PHONE :
 PARCEL . . . : 13-0610- - -0107- -24-
 APPL NUMBER: 15-50036199 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 05/20/2015 01:37 PM LBENNETT --
 HEAD NORTH ON HWY 421 TO TO COOL
 SPRINGS RD - TAKE RIGHT AND NEW
 HORIZONS WILL BE ON RIGHT
 PREMISE #70002614
 LAND NOTES : LXMN 9/14/04 SPLIT FROM THE 10 PARCEL

STRUCTURE: 000 000 45X66 3BDR W/GARAGE CRAWL


FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	8/27/15	TSG	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002709377
	8/27/15	AP	
B103 01	9/10/15	TSG	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002715274
	9/10/15	AP	T/S: 09/09/2015 09:27 AM KGOINS -----
A814 01	9/22/15	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002720829
	9/22/15	AP	121 STARLIGHT DR LILLINGTON 27546 T/S: 09/22/2015 09:04 AM SBENNETT -----
B105 01	9/22/15	TSG	R*OPEN FLOOR TIME: 17:00 VRU #: 002720811
	9/22/15	AP	T/S: 09/21/2015 09:58 AM LBENNETT -----
R425 01	11/12/15	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002739829
	11/12/15	DA	T/S: 11/10/2015 10:25 AM LBENNETT ----- 1- ROOF NOT COMPLETE 2- NEED ASSEMBLED TRUSS DOCUMENTS WITH LAY OUT PAGE.
R425 02	11/18/15	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002742427
	11/18/15	DA	1-house wrap needs to be over flashing at all roof areas 2-strap lvl in garage each side 3-install uplift protection on truss T1GRD
			OK TO INSULATE
R425 03	11/19/15	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002743433
	11/19/15	AP	T/S: 11/19/2015 08:43 AM SGUY -----
I129 01	12/04/15	TSG	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002748986
	12/04/15	AP	T/S: 12/03/2015 12:33 PM DJOHNSON -----
H824 01	3/09/16	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002787521
	3/09/16	AP	T/S: 03/10/2016 10:42 AM SSTEWARD ----- T/S: 03/10/2016 10:43 AM SSTEWARD -----
R429 01	4/08/16	MR	FOUR TRADE FINAL TIME: 17:00 VRU #: 002800431
	4/08/16	DA	T/S: 04/07/2016 10:53 AM LBENNETT ----- T/S: 04/08/2016 02:53 PM MREARIC ----- install house numbers seal around line-set entrance through foundation
R429 02	4/11/16	TSG	FOUR TRADE FINAL TIME: 17:00 VRU #: 002801454
	4/11/16	DA	1-CLEAR DEBRIS/TRASH FROM UNDER HOUSE 2-HEAT KIT MOCPC NOT INDICATED ON UNIT UNDER HOME.3-COVER SEWER DRAIN LINES AND GRADE AOUND HOME. 4-WIND LOAD STICKER NOT LOACATED ON GARAGE DOOR. 5-GARAGE STEPS INTO HOME HANDRAIL GRAB TOO

ADDRESS : 121 STARLIGHT DR
CONTRACTOR :
OWNER : BUCHANAN ROOFING INC
PARCEL : 13-0610- - -0107- -24-
APPL NUMBER: 15-50036199 CP NEW RESIDENTIAL (SFD)

SUBDIV: NEW HORIZONS
PHONE :
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			WIDE MAX 3.5 ALLOWED.6-SEAL ATTIC SCUTTLE ACCESS PANEL WITH WEATHER STRIP. 7-UNABLE TO LOCATE TEMPERED GLASS MARK ON WINDOW AT REAR ENTRY DOOR REQUIRED ON GLASS WITHIN TWO FEET.
R429 03	4/14/16 4/14/16	TSG DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002802643 T/S: 04/13/2016 10:17 AM DJOHNSON ----- ITEAM 7 FROM PREVIOUS INSPECTION NOT COMPLETE R308.4.2
R429 04	4/29/16	TI 	FOUR TRADE FINAL TIME: 17:00 VRU #: 002809267 T/S: 04/28/2016 08:46 AM LBENNETT -----

----- COMMENTS AND NOTES -----