COUNTY OF HARNETT Building Inspections Department Planning Services Certificate of Compliance:_____ Occupancy: Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following: Use Classification: Residentia **Permit Numbers** Name: Bradler Building: Electrical: Address: 2 Insulation: Plumbing: _ Mechanical: MFG Home: Date: 3-29-16 **Building Official:**

PREPARED 3/28/16, 14:27:14 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

3/29/16

ADDRESS . : 220 OXFORDSHIRE DR

SUBDIV: HADDEN POINTE II 18LOTS

CONTRACTOR : BRADLEY BUILT INC

PHONE: (919) 639-2073

OWNER . . : BRADLEY BUILT INC

R425 03

R429 01

2/17/16

2/17/16

3/28/16

3/28/16

BS

AP

BS

CA

PHONE :

PARCEL . . : 08-0652- - -0024- -30-

APPL NUMBER: 15-50037235 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 10/05/2015 09:08 AM JBROCK ----

HADDEN POINTE PH III #16R

STRUCTURE: 000 000 59X46 3BDR CRAWL W/ GARAGE & DECK

81904239

FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS 3000000.00 PROPOSED USE : SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY : COUNTY PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS -----B101 01 12/16/15 BS R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002754703 12/16/15 AP T/S: 12/15/2015 11:51 AM LBENNETT -----T/S: December 16, 2015 11:26 PM BSUTTON -----B103 01 1/05/16 BS R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002760403 1/05/16 AP T/S: 01/04/2016 08:29 AM DJOHNSON -----T/S: January 05, 2016 09:44 AM BSUTTON ------A814 01 1/07/16 SB ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002762086 1/07/16 AP 220 OXFORDSHIRE DR FUQUAY VARINA 27526 T/S: 01/07/2016 09:30 AM SBENNETT ------B105 01 1/07/16 R*OPEN FLOOR TIME: 17:00 VRU #: 002762094 BS 1/07/16 AP T/S: January 07, 2016 01:34 PM BSUTTON -----R425 01 FOUR TRADE ROUGH IN VRU #: 002772191 2/02/16 BS 2/02/16 DA T/S: February 02, 2016 11:32 AM BSUTTON ------1. Need engineers design for added cantilever at rear of house. Make sure letter addresses beam sizing, and footing /foundation as installed is suitable for added load. 2.Strap garage door opening per plan. 3. None of the plumbing is firestopped. 4. No more than two load bearing studs may be doubled and drilled at master bath vanity. 5. Need collar ties at rear porch roof. 6. Repair floor joist cut for master toilet plumbing. 7. Add a receptacle on living room side of kitchen kneewall on living room circuit. R425 02 2/10/16 DT FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002775351 2/10/16 DA T/S: 02/09/2016 11:27 AM LBENNETT ------T/S: 02/10/2016 11:20 AM DETAYLOR -----Still need receptacle for kitchen and collar ties for rear porch. Okay to side and insulate but leave porch framing visible 2/12/16 H824 01 JM ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002777530 2/12/16 AP T/S: 02/16/2016 11:39 AM SSTEWART ------T/S: 02/16/2016 11:40 AM SSTEWART ------I129 01 2/17/16 BS R*INSULATION INSPECTION TIME: 17:00 VRU #: 002777308 T/S: February 17, 2016 02:03 PM BSUTTON -----2/17/16 AP

FOUR TRADE ROUGH IN TIME: 17:00

T/S: February 17, 2016 02:03 PM BSUTTON ------

T/S: 03/24/2016 12:00 PM LBENNETT -----

T/S: March 28, 2016 11:16 AM BSUTTON -----

FOUR TRADE FINAL TIME: 17:00 VRU #: 002794543

VRU #: 002777324

PREPARED 3/28/16, 14:27:14 Harrett County

INSPECTION TICKET 14:27:14 INSPECTION TICK INSPECTOR: IVR

.....

PAGE

24 DATE 3/29/16

ADDRESS . : 220 OXFORDSHIRE DR

SUBDIV: HADDEN POINTE II 18LOTS

CONTRACTOR : BRADLEY BUILT INC

PHONE: (919) 639-2073

OWNER . . : BRADLEY BUILT INC

PHONE :

PARCEL . .: 08-0652- - -0024- -30-

APPL NUMBER: 15-50037235 CP NEW RESIDENTIAL (SFD)

REQUESTED INSP

REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

Not ready

R429 02 3/29/16 TI FOUR TRADE FINAL TIME: 17:00 VRU #: 002795318

------ COMMENTS AND NOTES ------