

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:**       X       **Occupancy:**       X      

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification:       R-3      

Name:       Weaver Dev.      

Address: \_\_\_\_\_

      160 Widgeon Way      

Date:       4-7-16      

**Permit Numbers**

Building:       15-50037703      

Electrical: \_\_\_\_\_

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

Building Official:       T. Michael Ream

ADDRESS : 160 WIDGEON WAY SUBDIV: THOMAS MANOR 36LOTS  
 CONTRACTOR : WEAVER DEVELOPMENT CO INC PHONE : (910) 433-0888  
 OWNER : WEAVER DEVELOPMENT COMPANY INC PHONE :  
 PARCEL : 13-0630- - -0096- -09-  
 APPL NUMBER: 15-50037703 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 12/14/2015 08:51 AM LBENNETT --  
 HWY 421 NORTH - LEFT ON NEILL THOMAS RD  
 - RIGHT ON OLD US 421 - LEFT INTO  
 THOMAS MANOR

**STRUCTURE: 000 000 56X59 SFD 3BDR W/GARAGE SLAB**  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW SEPTIC WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/21/16	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002767465
	1/21/16	AP	T/S: 01/21/2016 02:22 PM DETAYLOR -----
B103 01	1/27/16	TSG	R*BLDG FOUND & TEMP SVC POLE VRU #: 002769214
	1/27/16	AP	
A814 01	1/27/16	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002769222
	1/27/16	AP	160 WIDGEON WAY SPRING LAKE 28390 T/S: 01/27/2016 10:15 AM SBENNETT -----
P309 01	2/01/16	TSG	R*PLUMB UNDER SLAB VRU #: 002771269
	2/01/16	AP	
B111 01	2/03/16	TSG	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002772747
	2/03/16	AP	T/S: 02/02/2016 01:35 PM LBENNETT -----
R425 01	2/23/16	TSG	FOUR TRADE ROUGH IN VRU #: 002779513
	2/23/16	DA	1-STRAP LEFT GARAGE DOOR LVL 2-ANCHOR BOLT RIGHT SIDE GARAGE WALL. 3-REAR DOOR ANCHOR BOLT NUT MISSING 4-HEAD TEST DOWN 5-REAR MASTER BEDROOM WINDOW MISSING,
I129 01	2/24/16	TSG	R*INSULATION INSPECTION VRU #: 002780351
	2/24/16	DA	WINDOW STILL MISSING
R425 02	2/24/16	TSG	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002780567
	2/24/16	DA	WINDOW STILL NOT INSTALLED
H824 01	3/10/16	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002788289
	3/10/16	AP	T/S: 03/11/2016 10:25 AM SSTEWARD ----- T/S: 03/11/2016 10:26 AM SSTEWARD -----
E209 01	3/17/16	MR	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002790293
	3/17/16	AP	T/S: 03/16/2016 01:03 PM DJOHNSON ----- T/S: 03/17/2016 03:09 PM MREARIC -----
R429 01	3/28/16	TSG	FOUR TRADE FINAL VRU #: 002794088
	3/28/16	AP	
R429 02	4/07/16	TI	FOUR TRADE FINAL VRU #: 002799948

11 AP-IVR

COMMENTS AND NOTES

*This might be a duplicate*