

Harnett County
Application Tracking Action Log Maintenance

1/25/16
14:35:07

Application number : 16 50037904
Application type : CP NEW RESIDENTIAL (SFD)
Address : US 421
Revision/Path/Step/Seq/Agency: B 10 00 BUILDING PLAN REVIEW

13

Type information, press Enter.

Action date 12516
Action by (F4) MR MIKE REARIC
Action code (F4) HD
Time spent (hours)00
Correction report item N Y=Yes, N=No

1=Add new comment 2=Change comment 4=Delete comment

Opt Seq Comments

- 1.000 T/S: 01/25/2016 02:28 PM MREARIC -----
1. loads on master bedroom ceiling joists do not meet code
2. span of 2x10 SYP require #1 SYP, is that even
available?
3. have an engineer evaluate all structural loads T/S:
01/25/2016 02:33 PM MREARIC -----

Print
Y

F3=Exit F4=Prompt F9=Add standard comment F10=Force step complete
F12=Cancel F21=User defaults

+