

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: residential

Name: Loy + Brittany

Address: 1091 Nursery Rd

**Permit Numbers**

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: \_\_\_\_\_

Date: 5/15/17

Building Official: \_\_\_\_\_

[Signature]

ADDRESS : 8738 \*UNASSIGNED SUBDIV:  
 CONTRACTOR : MOSS KENNETH A PHONE : (910) 893-4875  
 OWNER : RAY JASON & BRITTANY PHONE :  
 PARCEL : 01-0536- - -0028- -03-  
 APPL NUMBER: 16-50037976 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : T/S: 02/05/2016 04:32 PM JBROCK ----  
 27 W L ON NURSERY RD PROPERTY PAST  
 DARROCH RD ON L @ 2 MILES


STRUCTURE: 000 000 66X66 3BDR CRAWL W/ GARAGE & DECK  
 FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3000000.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

| TYP/SQ  | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS  |
|---------|---------------------|-------------|---|
| A814 01 | 10/31/16            | SB          | ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002891547   |
|         | 10/31/16            | AP          | 1091 NURSERY RD LILLINGTON 27546<br>POST ADDRESS BY LONG DRIVE WAY<br>T/S: 10/31/2016 11:25 AM SBENNETT -----   |
| B101 01 | 10/31/16            | MR          | R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002891539   |
|         | 10/31/16            | AP          | T/S: 10/28/2016 12:41 PM JFORBES -----<br>T/S: 10/31/2016 02:40 PM MREARIC -----  |
| B103 01 | 11/22/16            | TSG         | R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002901577   |
|         | 11/22/16            | AP          | T/S: 11/21/2016 01:13 PM JBROCK -----   |
| B105 01 | 11/30/16            | TSG         | R*OPEN FLOOR TIME: 17:00 VRU #: 002904027   |
|         | 1/19/17             | AP          | T/S: 11/29/2016 10:08 AM JBROCK -----   |
| R425 01 | 1/19/17             | MR          | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002921708  |
|         | 1/19/17             | DA          | T/S: 01/18/2017 11:37 AM JBROCK -----<br>SOMEONE NEEDS TO SIGN OFF ON THE OPEN FLOOR INSPECTION<br>T/S: 01/19/2017 11:00 AM MREARIC -----<br>install fireblocking in chase by MBR entrance<br>ok to side and insulate |
| I129 01 | 1/30/17             | TSG         | R*INSULATION INSPECTION TIME: 17:00 VRU #: 002925493  |
|         | 1/30/17             | AP          | T/S: 01/27/2017 08:15 AM JBROCK -----<br>T/S: 01/30/2017 01:59 PM SGUY -----  |
| R425 02 | 1/30/17             | TSG         | FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002925501  |
|         | 1/30/17             | AP          | T/S: 01/27/2017 08:15 AM JBROCK -----<br>T/S: 01/30/2017 01:59 PM SGUY -----  |
| R125 01 | 4/10/17             | TSG         | ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002956365   |
|         | 4/10/17             | DA          | T/S: 04/07/2017 11:43 AM JBROCK -----<br>STONE INSPECTION<br>T/S: 04/10/2017 04:03 PM DJOHNSON -----<br>SEAL WINDOWS  |
| R125 02 | 4/12/17             | JH          | ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002957702   |
|         | 4/12/17             | DA          | T/S: 04/11/2017 01:42 PM JBROCK -----<br>stone inspection<br>1)Missing weep screed over windows.2)Need self furing lath<br>or self furing fastners.3)Lath not lapped 2" & installed<br>upside down in some places.    |
| R125 03 | 4/13/17             | TSG         | ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002959369   |
|         | 4/13/17             | AP          | T/S: 04/13/2017 02:59 PM JBROCK -----   |
| E209 01 | 4/27/17             | JH          | R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002964856   |

-----  
ADDRESS : 8738 \*UNASSIGNED SUBDIV:  
CONTRACTOR : MOSS KENNETH A PHONE : (910) 893-4875  
OWNER : RAY JASON & BRITTANY PHONE :  
PARCEL : 01-0536- - -0028- -03-  
APPL NUMBER: 16-50037976 CP NEW RESIDENTIAL (SFD)  
-----

| TYP/SQ  | REQUESTED COMPLETED | INSP RESULT | DESCRIPTION RESULTS/COMMENTS   |
|---------|---------------------|-------------|--|
|         | 4/27/17             | CA          | T/S: 04/26/2017 01:45 PM BPETRICH<br>PER KEN   |
| H824 01 | 4/28/17             | AC          | ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002966422  |
|         | 4/28/17             | AP          | T/S: 05/01/2017 11:15 AM KHINSON   |
| E209 02 | 5/01/17             | JH          | T/S: 05/01/2017 11:15 AM KHINSON   |
|         | 5/01/17             | AP          | R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002965408<br>T/S: 04/27/2017 01:10 PM JBROCK   |
| R429 01 | 5/05/17             | JH          | FOUR TRADE FINAL TIME: 17:00 VRU #: 002968576  |
|         | 5/05/17             | CA          | T/S: 05/04/2017 01:12 PM JBROCK<br>PER KEN   |
| R429 02 | 5/08/17             | JH          | FOUR TRADE FINAL TIME: 17:00 VRU #: 002969103  |
|         | 5/08/17             | DA          | T/S: 05/05/2017 01:45 PM JBROCK<br>1)Handrail at front porch doesn't meet code.2)Need wind load label for garage doors.3)Label dryer duct length per code.4)Energy certificate is missing window solar heat gain & u factor.5)Need permanent caps on drain line & water lines in attic not tape.6)Install hardware for attic door.7)Cover sewer & water lines & have 6" in 10' grade away from house.8)Need 8 1/4" max step on all exterior porches for bottom step. |
| R429 03 | 5/15/17             | TV          | FOUR TRADE FINAL TIME: 17:00 VRU #: 002971315<br>T/S: 05/11/2017 11:05 AM JBROCK   |



----- COMMENTS AND NOTES -----