## Harnett County Department of Public Health

24698

PERMIT # 29281

Operation Permit

	New Installation Septic Tank Nitrification Line Repair Expansion
	PROPERTY LOCATION: MINERAL Springs Zn. (Churcharte and Sh Mary)
Name: (owner) 2000 Constinction For.	PROPERTY LOCATION: Mineral Springs En. (Charlete et Sa Mary)  SUBDIVISION Avery Cond LOT # 37  Registration # 50 mineral Springs Lo
System Installer: Thereton's Charley	Registration #
Basement with plumbing: Garage Number of Bedrooms	4 50 Mineral Springs Lo
Type of Water Supply:  Community Public Well	Distance from well NA feet
System Type: 25% reduction 5,5. ZZT.	
(In accordance with Table V a)	Owner must contact Health Department 6 months prior to expiration for permit renewal.
This system has been installed in compliance with applicable North Carolina General Statutes, Rules for Sewage Treatment and Disposal, and all conditions of the Improvement Permit and Construction Authorization.	
	neoran Anell
	NOT Drawn to Scult
42	N. Jan.
-3- 1	110' 19'
	DOMEN DOMEN
Ay	ERY RE MINERAL SPRINCS LN
Performance: System shall perform in accordance with Rule .1961.   II. Monitoring: As required by Rule .1961. Other: Subsurface system operator required? Yes No lifyes, see attached sheet for additional operation conditions, maintenance and reporting.	
IV. Operation:	in conditions, maintenance and reporting.
Y. Other:	
	Alarm C Hooking C DWD I in
	Alarm
Following are the specifications for the sewage disposal system on the all Type of system:  Conventional  Other  exact length  Drainage Field  ditches  Linear feet	Septic Tank: 1250 gallons Pump Tank: 1350 gallons
-7-	
Authorized State Agent	Carr, 1848 Date 10/13/2017