"Setting the Standard for Service"

11. Buy the Complete Copyrige of the

043840

Coffee Constanting Section the first Engineering Fig. 3. 3.

September 14, 2017

17-50041143

Mr. Patrick Nolan Gary Robinson Homes 4140 Ramsey Street Fayetteville, NC 28304

> Reference: 33:3897-L4 Gary Robinson - Johnson Farms Lot 35 Lillington, North Carolina

Mr. Nolan,

ECS arrived onsite to observe the repair recommendations provided on Field Report #2 dated 9/7/17.

Based on our observations and random probing using a small steel diameter probe rod during today's visit, the materials in place appeared suitable for the placement of the designed concrete slab.

We appreciate the opportunity to work with you on this project. Should you have any questions or need additional information; please contact us at your earliest convenience.

Best Regards,

ECS SOUTHEAST, LLP

Ryan Parrish Project Manager

Project Engineer