PREPA 5/09/18, 14:06:08 INSPECTION TICKET PAGE 34
Harnet County INSPECTOR: IVR DATE 5/10/18

ADDRESS . : 192 MILLWOOD LN SUBDIV: ADAMS FARMS SUBDIVISION

CONTRACTOR: PHONE:
OWNER..: COOPER ROBIN W JT W/ROS & WOOD PHONE:

PARCEL . . : 04-0673- - -0121- -12-

APPL NUMBER: 18-50043039 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: T/S: 01/08/2018 08:59 AM LLUCAS ---TRAVEL HWY 210 TOWARDS HWY 55 IN ANGIER
- MILLWOOD LN WILL BE ON YOUR RIGHT THE LOT IS THE LAST ONE ON THE RIGHT THE ONLY LOT WITHOUT A HOUSE BUILT

STRUCTURE: 000 000 54X60 4BDR 3BTH W/GARAGE CRWL

FLOOD ZONE . . . : FLOOD ZONE X

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD				
	REQUESTED	INSP	DESCRIPTION	
TYP/SQ	COMPLETED		RESULTS/COMMENTS	
	2/14/18	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003089042	
	2/15/18	AP	192 MILLWOOD LN ANGIER 27501	
			T/S: 02/15/2018 11:04 AM SBENNETT	
B101 01	2/20/18	MC	R*BLDG FOOTING / TEMP SVC POLE VRU #: 003091371	
	2/20/18	AP	T/S: 02/20/2018 03:09 PM MCOOK	
			1. did not inspect 5 deck footing will check at later time	
B103 01	3/12/18	MC	R*BLDG FOUND & TEMP SVC POLE VRU #: 003099881	
	3/12/18	AP	T/S: 03/12/2018 02:02 PM MCOOK	
B101 02	3/15/18	MC	R*BLDG FOOTING / TEMP SVC POLE VRU #: 003101912	
	3/15/18	AP	T/S: 03/15/2018 01:43 PM MCOOK	
			1. called in at 9:15am	
B105 01	3/19/18	MC	R*OPEN FLOOR VRU #: 003101841	
	3/19/18	DA	T/S: 03/19/2018 02:23 PM MCOOK	
			1. 31vl support on 2-2x10 header at crawl door , need	
			engineer of record to look at to make sure load ok	
R425 01	4/24/18	MC	FOUR TRADE ROUGH IN VRU #: 003116860	
	4/24/18	DA	HVAC and Plumbing would like to be there during the	
			inspection. If you could please text or call me Tuesday	
			morning at 919-414-6534 so I can let them know an estimated	
			time you will be at the house that would be great! Thank	
			you	
			0/S: 04/24/2018 03:52 PM MCOOK	
			 properly install (attach) firebox 2. properly flash 	
			around front porch 3. install all air barrier where	
			required 4. install all fire/draft stop 5. install baffles	
			upstairs 6. missing nail plate at hall bath behind shower	
			valve 7. air test low	
R425 02	4/30/18	MC	FOUR TRADE ROUGH IN VRU #: 003119872	
	4/30/18	AP	If you can make it the afternoon of Friday the 27th that	
			would be great. If not, have a great weekend!	
			T/S: 04/30/2018 03:25 PM MCOOK	
I129 01	5/07/18	TI	R*INSULATION INSPECTION VRU #: 003123320	
	5/04/18	CA	The front and back porch concrete are supposed to be done	
			on Monday (I hope), as well as the garage. If there is	
			anyway for someone to come early for the inspection that	

------ CONTINUED ONTO NEXT PAGE ------

5/09/18, 14:06:08 Haznet County

INSPECTION TICKET INSPECTOR: IVR

PAGE 35

DATE 5/10/18

ADDRESS . : 192 MILLWOOD LN

SUBDIV: ADAMS FARMS SUBDIVISION

CONTRACTOR :

PHONE :

OWNER . . : COOPER ROBIN W JT W/ROS & WOOD

PHONE :

PARCEL . . : 04-0673- - -0121- -12-

APPL NUMBER: 18-50043039 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			would be great. Otherwise we may need to get a rope to swing over the front porch! :)
B105 02	5/09/18 5/07/18	TI CA	R*OPEN FLOOR VRU #: 003123809
I129 02	5/09/18 5/07/18	TI CA	R*INSULATION INSPECTION VRU #: 003123742 If possible, please inspect in the morning. Thanks so much!
B105 03	5/10/18	TI AC	R*OPEN FLOOR VRU #: 003124666
I129 03	5/10/18 	TI	R*INSULATION INSPECTION VRU #: 003124674

------ COMMENTS AND NOTES --------

Mark E. Jones, PE Structural Engineering and Design

March 20, 2018

Karen Wood 192 Millwood Lane Angier, NC 27501

Ref: Site Observations and Analysis

192 Millwood Lane

Angier, NC

Project No. 17-298

To Whom it may concern;

The above referenced site was observed on March 19, 2018 for the following items:

1. Verify header above crawl access.

Based on analysis, the conclusions regarding the condition(s) are:

1. The builder has provided a 2-2x10 header across the crawl access opening. There is floor and roof load as well as a point load at this location. The 2-2x10 header is adequate to support the imposed loads. No action is required.

Thank you for this opportunity to assist you. If you have any questions or need any further assistance, please do not hesitate to all CARO.

Respectfully.

Mark E. Jones, PE