


FACTORS		PI ES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-36	0-36	0-38						
Texture Group	.1941(A)(1)	LSL	LSL	LSL						
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	<del>—</del>	—	—						
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948	5	5	5						
LONG TERM ACCEPTANCE RATE	.1955	8	8	8						

2x80' lines  
18"-24" deep



Sierra Trail 60'R/W



SITE PLAN APPROVAL

DISTRICT N/A USE SFD

#BEDROOMS 3

Date 12-8-99 Zoning Administrator Jessica Byrd

Montana Lane 60'R/W

Plot Plan  
Price Construction Company

Sierra Villa Subdivision

PC #

Anderson