

www.harnett.org

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

> ph: 910-893-7547 fax: 910-893-9371

January 25, 2019

Paul E. Fowler 950 US 401 South Lillington, NC 27546

RE: Third sample of Bacteriological water sample collected at: 950 US 401 South EH 1811-0004

Dear Mr. Fowler,

The report of your water sample taken for bacteria, revealed the presence of Total Coli form. A copy of the water sample report is enclosed.

The enclosed pamphlet provides specific directions about how to disinfect the well. If you have any questions regarding disinfection, contact the Fayetteville Regional Office at (910) 433-3300 or contact me at (910) 893-7547.

As soon as the well has been treated, contact the Harnett County Division of Environmental Health so another sample can be taken. No fee will be charged for a second sample if the request is made within thirty (30) days of this letter. After thirty (30) days, the fee for a second sample is \$25.00.

If you have any questions, please call me Monday through Friday between 8:00 and 9:00 a.m. at (910) 893-7547.

Sincerely,

Andrew Currin, R.E.H.S.

Environmental Health Specialist

Harnett County Department of Public Health

AC/sags

Enclosures: Water Sample Report

Biological Analysis Report

How to Disinfect Your Water Well



North Carolina State Laboratory of Public Health

Environmental Sciences

Microbiology **Certificate of Analysis**

4312 District Drive MSC 1918

Raleigh, NC 27699-1918

http://slph.ncpublichealth.com Phone: 919-733-7308 Fax: 919-715-8611

FINAL REPORT

Report to: ANDREW CURRIN

HARNETT CO ENVIRONMENTAL HEALTH

307 CORNELIUS HARNETT BLVD

Lillington, NC 27546

Name of System:

Paul E Fowler

950 US 401 S

Lillington, NC 27546

EIN: 566000306EH

Delivery: NC Courier

Harnett County

StarLiMS ID: ES190115-0075

Date Collected: Date Received: 01/14/2019 01/15/2019 Time Collected:

15:30

By:

Adam Currin

Sample Source:

Well water

Sampling Point:

Rear spigot

Time Received:

09:13

Angela Heybroek By:

Sample Type:

GPS No.

Well Permit No.

Comment:

Treatment:

Colilert Profile

Method: SM 9223B

Analyte	Test Result	Unit	Conclusion	Date Tested
Total Coliform	Present			01/15/2019
E. coli	Absent			01/15/2019

Report Date: 01/18/2019

Reported By:

Susan Beasley

Explanations of Coliform Analysis:

If coliform bacteria are Absent, the water is considered safe for drinking purpose. If coliform bacteria are Present, the water is considered unsafe for drinking purpose. Presence of E. coli (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.

North Carolina Division of Public Health Occupational and Environmental Epidemiology Branch, Epidemiology Section BIOLOGICAL ANALYSIS REPORT

Private well water information and recommendations ES190115-0075 County: Harnett Name: Paul E. Fowler Sample ID Number:
Location: 950 05 401 5. Lillington, NC 27546 Reviewer Andrew Corrin, REHS Initial Sample Confirmation Sample BIOLOGICAL ANALYSIS RESULTS AND RECOMMENDATIONS FOR USES OF YOUR PRIVATE WELL WATER (These recommendations are based on biological analysis only.) No coliform bacteria were found in your well water. Your water can be used for all purposes including drinking, cooking, washing dishes, bathing and showering. Total coliform bacteria were detected in the sample which indicates that harmful bacteria from human or animal waste could enter the well. Do not use the water for drinking or cooking unless it has been boiled for 3 minutes. You may use your water for all other purposes including washing dishes, bathing or showering. Your well water needs to be re-tested to verify that the result is accurate. Fecal coliform bacteria were detected in the sample. Do not use the water for drinking, cooking, washing dishes, bathing or showering. If the re-test shows contamination by bacteria contact your local health department for

assistance. There may be a problem with the construction of the well, the groundwater source, or operation of the well. The well needs to be inspected by the local health department or a local well contractor to determine the problem with the well and to give guidance on how to correct the problem.

Your well water was tested for biological contaminants (total coliform and fecal coliform bacteria). The results were evaluated using the federal drinking water standards.

Drinking water may contain substances that can occur naturally in water or can be introduced into water from man-made sources. Total coliform bacteria are found in soil and fecal coliform bacteria are found in animal and human waste. Total coliform or fecal coliform bacteria in well water indicate that the well may have structural problems or that the well was not properly disinfected.

If you have been drinking the well water and are pregnant, nursing, have a child in the household under 5 years of age, or immunocompromised (such as an individual with AIDS, cancer, hepatitis, dialysis or surgical procedures) inform your physician of these results at your next visit.

If the contamination continues, you should investigate the possibility of drilling a new well or installing a point-of-entry disinfection unit which can use chlorine, ultraviolet light, or ozone.

For further information please contact your county health department or the Occupational and Environmental Epidemiology Branch at 919-707-5900.