

www.harnett.org

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

> ph: 910-893-7547 fax: 910-893-9371

March 20th, 2020

Willie Williams 422 Rafter Creek Lane Sanford, NC 27332

RE: Bacteriological water sample collected at: 422 Rafter Creek Lane

Dear Mr. Williams,

The report of your water sample taken for bacteria, revealed the presence of Total Coli form. A copy of the water sample report is enclosed. The enclosed pamphlet provides specific directions about how to disinfect the well.

- If you have any questions regarding *disinfection*, contact the Fayetteville Regional Office at (910) 433-3300.
- If you have questions regarding *results* (*limitations or levels*, *specific health hazards*) etc. they can be directed to the N. C. State Laboratory of Public Health in Raleigh, N. C., Environmental Sciences, and Microbiology Division at (919) 733-7308.

As soon as the well has been treated, contact the Harnett County Division of Environmental Health so another sample can be taken. No fee will be charged for a second sample if the request is made within thirty (30) days of this letter. After thirty (30) days, the fee for a second sample is \$25.00.

Feel free to contact me with any further questions, or for a resample. I may be reached Monday through Friday between 8:00 and 9:00 a.m. at (910) 893-7547.

Sincerely.

Brittany Adams, R.E.H.S.I

Environmental Health Specialist

Harnett County Department of Public Health

BA/kh

Enclosures: Water Sample Report

Biological Analysis Report

How to Disinfect Your Well Instructions

ach REHIS-I