

December 2, 2020

Harnett County Government Complex  
307 W. Cornelius Harnett Boulevard  
Lillington, NC 27546

ph: 910-893-7547

fax: 910-893-9371

**Re: Status of Repair Permit for: 25 Doug Johnson Lane Angier, NC 27501**

Mr. Johnson:

An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Use pink flags to mark property lines and irons that are set by surveyor need to be visible.
- 2. Use orange flags to mark house corners (*\$25.00 fee incurred*)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Property needs only brush or vegetation removed
- 5. Driveway not shown on site plan
- 6. Backhoe pits required
- 7. Other-General maintained advised pre-permitting repair. Applicant notified via phone. Wet spot present at end of drain line. Advised to check D-Box for equal distribution to both line, relocate gutter drainage away from septic area, and place dry sand at end to attempt drying wet area. Wet area may be caused by excessive gutter drainage onto first line. Reconfirm if problems persists.**

Your application will be put on hold until the selected items above have been addressed.

When completed **please call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R.E.H.S.  
Environmental Health Specialist  
Harnett County Department of Public Health

AC/slc

Copy: Central Permitting  
Enclosures