

www.harnett.org

January 21, 2021

Harnett County Government Complex 307 W. Cornelius Harnett Boulevard Lillington, NC 27546

Doug Lynn 824 Chalybeate Springs Road Angier NC 27501

ph: 910-893-7547 fax: 910-893-9371

Re: Status of Repair Permit for: 824 Chalybeate Springs Road Angier, NC 27501

Mr. Lynn:

An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.

	<ol> <li>Use pink flags to mark property lines and irons that are set by surveyor need to be visible.</li> </ol>
	2. Use orange flags to mark house corners (\$25.00 fee incurred)
	3. Directions not clear to property (\$25.00 fee incurred)
	4. Property needs only brush or vegetation removed
	5. Driveway not shown on site plan
	6. Backhoe pits required
v	7 Other- County documentation reflects lot is significantly smaller th

X 7. Other-County documentation reflects lot is significantly smaller than onsite surveyed property. Owner shall coordinate with surveyor and provide new revised survey map and/or provide documentation of existing deeded property that surveyor used to mark property. Secondly, owner shall determine if existing well is present in well house. If so, well abandonment shall be filed.

Your application will be put on hold until the selected items above have been addressed. When completed **please call 910-893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Andrew Currin, R.E.H.S.

Environmental Health Specialist

Harnett County Department of Public Health

AC/slc

Copy: Central Permitting

Enclosures