

March 17, 2021

Carolyn Dorman
205 Pineview Drive
Erwin, NC 28339

RE: New Well Construction Application # EH2102-0027

Ms. Dorman:

An attempt was made to evaluate your property for the purpose of issuing a new well construction permit. The evaluation could not be completed for one or more of the following reasons.

____ 1. Uncover Outlet lid on septic tank and break seal. (\$25.00 fee incurred).

____ 2. Have system pumped out

____ 3. Replace Sanitary T

X 4. **Other – Well maintenance/Testing advised. Existing well onsite. Applicant stated renters complained of odd water. Advised to contact well company to provide well testing and filtration of existing well. Well testing can be applied for and provided by Harnett County. Multiple filtration and sanitation possibilities exist with well companies. New well permitting is possible but not advised until after exhausting all existing well possibilities.**

Your application will be put on hold until the selected items above have been addressed. When completed, **call (910) 893-7547 to confirm** that the items mentioned have been corrected we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R. E. H. S.
Environmental Health Program Specialist
Harnett County Department of Public Health

AC/slc
Copy - Central Permitting