HARNETT COUNTY DEPARMENT OF PUBLIC HEALTH Well Abandonment Permit

Permit Number:

Application Number: EH2112-0019

Applicant Name: Carlos Llamas

Address: 4917 Marks Rd (SR 1111)

Type of Well:Bored Total Depth: 30Ft Diameter: 24in Grouted: Static Water Level: 10Ft

Directions to Site:

Agent of the State Mal REHI Date: 1-27-22

Abandonment Procedure: Abandonment Procedure: 1. Remove all plumbing or piping into the well, along with any obstructions inside the well; 2.Remove as much of the well tile casing a possible, but no les than to a depth of three feet below land surface; 3, remove all soil or other subsurface material present down to the top of the remaining well easing, and extending to a width of at least 12 inches outside of the well easing on all sides; 4. Fill the well up to the top of the remaining easing with cement grout, concrete grout, bentonite grout, dry clay, or material excavated during drilling of the well and then compacted in place; 5. Pour a one foot thick concrete grout or cement grout plug that fills the entire excavated area about the top of the casing, including the area extending on all sided of the casing out to a width of at least 12 inches on all sides; 6. Complete the abandonment process by filling the remainder of the well above the concrete or cement plug with additional concrete grout, cement grout, or soil. A record of the abandonment must be submitted within 30 days of abandonment.

Note: Contact Harnett County Environmental Health for appointment prior to beginning of well abandonment procedure.

Well must be abandoned by a Certified North Carolina well driller/contractor. egal Representative Signature Required

WELL ABANDONMENT RECORD		For Internal Use ONLY:					
R-15 - C							
1. Well Contractor Information: BENFORD CAR-HAM CRAHAM & CHARE D.C. LLL Well Contractor Name (or well owner personally abandoning well on his/her property) 2773-A		WELL ABANDONMENT DETAILS					
		7a. For Geoprobe/DPT or Closed-Loop Geothermal Wells having the same well construction/depth, only 1 GW-30 is needed. Indicate TOTAL NUMBER of wells abandoned:					
				NC Well Contractor Certification Number		7b. Approximate volume of water remaining in well(s):(gal.) FOR WATER SUPPLY WELLS ONLY:	
				Construct wage De Daille a Co			
Company Name							
2. Well Construction Permit #: \(\begin{align*} \b		7c. Type of disinfectant used: Hypochlolite					
		211 000					
		7d. Amount of disinfectant used: 3	12 OUKes				
3. Well use (check well use):							
Water Supply Well:		7e. Sealing materials used (check all the	hat apply):				
□ Agricultural	□Municipal/Public	□ Neat Cement Grout	☐ Bentonite Chips or Pellets				
☐Geothermal (Heating/Cooling Supply)	Residential Water Supply (single)	□ Sand Cement Grout	□ Dry Clay				
□Industrial/Commercial	□Residential Water Supply (shared)	Concrete Grout	□ Drill Cuttings				
□lrrigation Non-Water Supply Well:		□ Specialty Grout	□ Gravel				
□Monitoring	□Recovery	☐ Bentonite Slurry	☐ Other (explain under 7g)				
Injection Well:		7f. For each material selected above, p	provide amount of materials used:				
☐ Aquifer Recharge	☐Groundwater Remediation	7 hols					
☐ Aquifer Storage and Recovery	□Salinity Barrier	1900					
□ Aquifer Test	☐Stormwater Drainage						
□Experimental Technology	□Subsidence Control	7g. Provide a brief description of the a	handonment procedure				
□Geothermal (Closed Loop)	□Tracer	^					
Geothermal (Heating/Cooling Return)	□Other (explain under 7g)	Removed Top Sach!					
4. Date well(s) abandoned 2/24/2022		Add 31/202 Hypoc	Horitato Disinfect.				
		fill- 1/1/2/11/2/1	Elizable concrete				
5a. Well location:		filled Well W/FlowAble concrete					
CACINS LIAMAS		PLACE OVERBUSE	len over Top of conc				
Facility/Owner Name	Facility ID# (if applicable)	& Certification:	,				
4917 MAINE ROM	1 0	5					
June / hale			24 FEB 2				
Physical Address, City, and Zip		Signature of Cortified Well Contractor or Well	Owner Date				
HARNETT		By signing this form, I hereby certify I	that the well(s) was (were) abandoned in				
County Parcel Identification No. (PIN)		accordance with 15A NCAC 02C .0100 or 2C .0200 Well Construction Standards					
5b. Latitude and longitude in degrees/minutes/seconds or decimal degrees:		and that a copy of this record has been provided to the well owner.					
(if well field, one lat/long is sufficient)		 Site diagram or additional well details: You may use the back of this page to provide additional well site details or well abandonment details. You may also attach additional pages if necessary. 					
35.20822 N 19.11365 W							
CONSTRUCTION DETAILS OF WELL(S) BEING ABANDONED			or additional pages it necessary.				
Attach well construction record(s) if available. For multiple injection or non-water supply wells		SUBMITTAL INSTRUCTIONS					
ONLY with the same construction abandonment,	you can submit one form.	10a. For All Wells: Submit this form	n within 30 days of completion of well				
6a. Well ID#:		abandonment to the following.					
2 40		Division of Water Resources	, Information Processing Unit,				
6b. Total well depth: 30	(ft.)	1617 Mail Service Cente	r, Raleigh, NC 27699-1617				
2/1		10b. For Injection Wells: In addition	to sending the form to the address in 10a				
6c. Borehole diameter: (in.)		above, also submit one copy of this for	rm within 30 days of completion of well				
	5 0	abandonment to the following					
6d. Water level below ground surface: 28 (ft.)			rground Injection Control Program,				
			r, Raleigh, NC 27699-1636				
6e. Outer casing length (if known):	(ft.)		ells: In addition to sending the form to the				
	,		of this form within 30 days of completion health department of the county where				
6f. Inner casing/tubing length (if known)	(ft.)	abandoned.	department of the county where				
a man (man)	(111)						

6g. Screen length (if known): ___