Evaluation Re-evaluation	/
	(number)

North Carolina Department of Environment and Natural Resources

Division of Environmental Health

PREOCCUPANCY EVALUATION REPORT OF DRINKING WATER SUPPLY AND WASTEWATER FACILITIES FOR MIGRANT HOUSING

On 3-//-25, as required in G.S. 95-225(c) and (d), an evaluation was conducted of the drinking water supply and
wastewater system serving a migrant nousing site composed of # of/_ Inobite florite units, # of/_ Flourise (s) and
Other type of housing/describe: located at 620 Holly Spring Church 100
Broodway NC 27505 and operated by Phillip Ryan Patterson
(name of person[s]/company)
(mailing address)
wastewater system serving a migrant housing site composed of # of / Mobile home units, # of O House (s) and Other type of housing/describe: located at 620 Holly Spring Church Note (address or directions, use reverse if needed)
This report describes well/spring/ and sewage system/ (use reverse for a drawing, if needed.)
The findings of this evaluation are as follows:
WATER SUPPLY
Community or non-transient-non-community water system under routine surveillance of Public Water Supply Section,
(yes/no) Division of Environmental Health
At the time of inspection, there WH NoT visual evidence of non-compliance with the "Protection of Water Supplies" (was/was not)
15A NCAC 18A .1700 (attach copy of bacteriological sample). List deficiencies which were identified:
(Use reverse if necessary)
(Obb 1010100 ii nobbookily)
WASTEWATER FACILITIES
Systemto approval under 15A NCAC 18A .1900, "Laws and Rules for Sewage Treatment and Disposal
(subject/not subject)
Systems." Explain, if not subject to approval
On-Site Septic Tank System [] Chemical Portable Toilets [] Others [] Privy(ies)
At the time of inspection, there WK NoT visual evidence of non-compliance with 15A NCAC 18A .1900 (including
(was/was not)
.1962) "Laws and Rules for Sewage Treatment and Disposal System." List deficiencies which were identified:
(Use reverse if necessary)
5
The wastewater system, to the best of my knowledge and belief, is sized to servepeople. (maximum number)
Mariett County Environmental Health
Environmental Health Specialist Health Department
3-17-25 307 W. Cornelius Harnett Blvd.
Date Address
Forward copies to: Migrant Housing Operator Lillington, NC 27546
Department of Labor
Agriculture Safety & Health Bureau 910-893-7547 Office Phone Number

DENR 3765 (Revised 2/2011)
On-Site Wastewater Section (Review 12/2010)



North Carolina State Laboratory of Public Health

Environmental Sciences

Microbiology Certificate of Analysis

4312 District Drive MSC 1918 Raleigh, NC 27699-1918

http://slph.ncpublichealth.com Phone: 919-733-7308 Fax: 919-715-8611

FINAL REPORT

Report to: M Osborne

HARNETT CO ENVIRONMENTAL HEALTH

307 CORNELIUS HARNETT BLVD

Lillington, NC 27546

Name of System:

Phillip Ryan Patterson

620 Holly Spring Ch Rd Broadway, NC 27505

EIN: 566000306EH

Delivery:

NC Courier

Harnett County

StarLiMS ID: ES250312-0050

Date Collected:

03/11/2025

Time Collected:

12:55

M. Osborne By:

Bv:

Date Received:

03/12/2025

Time Received:

07:58

DeMonta Newborn

Sample Source: Well water Sample Type:

Sampling Point:

Outside tap

GPS No.

Treatment:

Well Permit No.

Comment:

Colilert Profile

Analyte

Test Result Unit

Conclusion

Method: SM 9223B **Date Tested**

03/12/2025

Total Coliform E. coli

Absent

Absent

03/12/2025

Report Date:

03/14/2025

Reported By:

KKURTZ

Explanations of Coliform Analysis:

If coliform bacteria are Absent, the water is considered safe for drinking purpose. If coliform bacteria are Present, the water is considered unsafe for drinking purpose. Presence of E. coli (bacteria) generally indicates that the water has been contaminated with fecal material. It must be remembered that a water analysis refers only to the sample received and should not be regarded as a complete report on the water supply.

North Carolina Division of Public Health Occupational and Environmental Epidemiology Branch, Epidemiology Section BIOLOGICAL ANALYSIS REPORT

Private well water information and recommendations

County: Home TT Name: Philip Ryon Patterson Sample ID Number: ES 750312 -00: Location: 620 Actly Spring Church As Broadway Reviewer Mashorm	
Location: 620 Actly Spring (With 14) Broadony Reviewer 17 Osbor	
N 2/303	
Initial Sample Confirmation Sample	
BIOLOGICAL ANALYSIS RESULTS AND RECOMMENDATIONS FOR USES OF YOUR PRIVATE WELL WATER (These recommendations are based on biological analysis only.)	
No coliform bacteria were found in your well water. Your water can be used for all purposes including drinking, cooking, washing dishes, bathing and showering.	
Total coliform bacteria were detected in your water sample. Total Coliform are a group of related bacteria that are (with few exceptions) not harmful to humans. A variety of bacteria, parasites, and viruses, known as pathogens, can potentially cause health problems if humans ingest them. EPA considers total coliforms a useful indicator of other pathogens for drinking water. Total coliforms are used to determine the adequacy of water treatment and the integrity of the distribution system	
It is recommended that your well water be re-tested to verify that the result is accurate.	
Fecal coliform bacteria were detected in the sample. Do not use the water for drinking, cooking, washing dishes, bathing or showering.	
If the re-test shows contamination by bacteria contact your local health department for assistance. There may be a problem with the construction of the well, the groundwater source, or operation of the well. The well needs to be inspected by the local health department or a local well contractor to determine the problem with the well and to give guidance on how to correct the problem.	
Your well water was tested for biological contaminants (total coliform and fecal coliform bacteria). The results were evaluated using the federal drinking water standards.	

If you have been drinking the well water and are pregnant, nursing, have a child in the household under 5 years of age, or immunocompromised (such as an individual with AIDS, cancer, hepatitis, dialysis or surgical procedures) inform your physician of these results at your next visit.

Drinking water may contain substances that can occur naturally in water or can be introduced into water from man-made sources. Total coliform bacteria are found in soil and fecal coliform bacteria are found in animal and human waste. Total coliform or fecal coliform bacteria in well water indicate that the well

If the contamination continues, you should investigate the possibility of drilling a new well or installing a point-of-entry disinfection unit which can use chlorine, ultraviolet light, or ozone.

For further information please contact your county health department or the Occupational and Environmental Epidemiology Branch at 919-707-5900.

may have structural problems or that the well was not properly disinfected.