

2B Services Inc
PO Box 2068
Fayetteville NC 28302

TEST RESULTS

Property Address 264 Trickland

New Home _____ Existing Home

Builder _____ HVAC Contractor Total Systems

HVAC Number 1 Describe area of home served Front

CFM 25 Total 65 Conditioned Floor Area(CFA) served by system 1491 s.f.

CFM 25X100 divided by CFA = 4.4 CFM25/100 SF

Fan Attachment Location Return PASS FAIL

Robt M. Zumpf 6-27-19
Signature of Tester Date

NC Licensed HVAC Contractor

2B Services Inc
PO Box 2068
Fayetteville NC 28302

TEST RESULTS

Property Address 26 Strickland

New Home _____ Existing Home

Builder _____ HVAC Contractor Total Systems

HVAC Number 2 Describe area of home served Back

CFM 25 Total 57 Conditioned Floor Area(CFA) served by system 1491 s.f.

CFM 25X100 divided by CFA = 3.8 CFM25/100 SF

Fan Attachment Location Return (PASS/ FAIL)

Billy Mc 2 Jr. 6-27-19
Signature of Tester Date

NC Licensed HVAC Contractor