

Application # \_\_\_\_\_

**Harnett County Central Permitting**

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits  
Certification of Work Performed By Owner/Contractor  
(Individual Trade Application)

Owner (s) of Structure: MARY HOLMES Phone: 910-514-4122

Owner (s) Mailing Address: 1635 TIM CURRIN RD LILLINGTON NC 27546

Land Owner Name (s): MARY HOLMES Phone: 910-514-4122

Construction or Site Address: 1635 TIM CURRIN RD LILLINGTON NC 27546

PIN # 0529-41-1895.000 Parcel # 130621 0006 04

Job Cost: 10296.00 Description of Work to be done: REPLACE WHOLE HOUSE HEAT PUMP SYSTEM  
DUCT MODS AND ZONE SYSTEM IN ATTIC

Mechanical: New Unit With Ductwork \_\_\_ New Unit Without Ductwork  Gas Piping \_\_\_ Other \_\_\_

Electrical\*: 200 Amp \_\_\_ <200 Amp \_\_\_ Service Change \_\_\_ Service Reconnect \_\_\_ Other

\* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap \_\_\_ Number of Baths \_\_\_ Water Heater \_\_\_

Specific Directions to Job from Lillington:

Subdivision: WALKERS CREEK EST Lot #: 7

I ARS will provide the MECHANICAL/ELECTRICAL labor on this structure.  
(Contractors Name) (Trade)

I am the building owner or my NC state license number is 23253/28807, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

AMERICAN RESIDENTIAL SERVICES LLC  
Contractor's Company Name  
517 PYLON DRIVE RALEIGH NC 27606  
Address  
23253/28807  
License #

919-861-0883  
Telephone  
8876INSPECTIONS@ARS.COM  
Email Address

Structure Owner / Contractor Signature:  Date: 5/1/2020

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

**\*Company name, address, & phone must match information on license**