

Application # \_\_\_\_\_

**Harnett County Central Permitting**

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

**Certification of Work Performed By Owner/Contractor  
(Individual Trade Application)**

Owner (s) of Structure: 153 BRANDYWOOD CT CAMERON NC 28326 Phone: 910-494-4544

Owner (s) Mailing Address: 153 BRANDYWOOD CT CAMERON NC 28326

Land Owner Name (s): TIM BURGESS Phone: 910-494-4544

Construction or Site Address: \_\_\_\_\_

PIN # \_\_\_\_\_ Parcel # \_\_\_\_\_

Job Cost: 4699.00 Description of Work to be done INSTALLING NEW MINI SPLIT IN BUILDING  
BEHIND HOME

Mechanical: New Unit With Ductwork \_\_\_ New Unit Without Ductwork  Gas Piping \_\_\_ Other \_\_\_

Electrical\*: 200 Amp \_\_\_ <200 Amp \_\_\_ Service Change \_\_\_ Service Reconnect \_\_\_ Other

\* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap \_\_\_ Number of Baths \_\_\_ Water Heater \_\_\_

Specific Directions to Job from Lillington:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subdivision: \_\_\_\_\_ Lot #: \_\_\_\_\_

I ARS will provide the MECHANICAL/ELECTRICAL labor on this structure.  
(Contractors Name) (Trade)

I am the building owner or my NC state license number is 29147/28807, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

AMERICAN RESIDENTIAL SERVICESLLC dba ARS

919-861-0883

Contractor's Company Name

Telephone

517 PYLON DRIVE RALEIGH NC 27606

8876INSPECTIONS@ARS.COM

Address

Email Address

29147/28807

License #

Structure Owner / Contractor Signature:  Date: 9/1/2020

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

**\*Company name, address, & phone must match information on license**