

Harnett County Central Permitting

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

**Certification of Work Performed By Owner/Contractor
(Individual Trade Application)**Owner (s) of Structure: Mason Terrell Phone: (910) 330-8606Owner (s) Mailing Address: 33 Macon Court East Sanford, NC 27332Land Owner Name (s): Mason Terrell Phone: (910) 330-8606Construction or Site Address: 33 Macon Court East Sanford, NC 27332

PIN # _____ Parcel # _____

Job Cost: \$6,177 Description of Work to be done _____
Changeout and Reconnect 3.5 Ton Heat Pump & Air Handler located in attic. Unit serves whole house – Like for Like.Mechanical: New Unit With Ductwork ____ New Unit Without Ductwork ☒ Gas Piping ____ Other ____Electrical*: 200 Amp ____ <200 Amp ____ Service Change ____ Service Reconnect ____ Other ____
* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap ____ Number of Baths ____ Water Heater ____

Specific Directions to Job from Lillington:

Subdivision: _____ Lot #: _____

I Jimmy Pierce/Joel Worsham will provide the mechanical/electrical labor on this structure.
(Contractors Name) (Trade)I am the building owner or my NC state license number is 18855/21474, which entitles me to
perform such work on the above structure legally. All work shall comply with the State Building Code and all
other applicable State and local laws, ordinances and regulations.Comfort First Heating and Cooling
Contractor's Company Name
7001 Lark Lane, Sanford NC 27332
Address
18855/21474
License # _____919-569-5161
Telephone
installadmin@yourcomfortfirst.com
Email AddressStructure Owner / Contractor Signature: Jimmy Pierce & Joel Worsham Date: 9/8/2025By signing this application you affirm that you have obtained permission from the above listed license holder to
purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell
the listed property for 12 months after completion of the listed work.***Company name, address, & phone must match information on license**