

January 22, 2014

John E. Homan
12638 NC Hwy 42
Holly Springs, NC 27540

RE: Failing system located at: Duncan Junction – 12638 NC 42 Holly Springs, NC

Dear Mr. Homan,


An on-site inspection was made on your property on January 17, 2014 by an Environmental Health Specialist and observed a failing septic system. Since we already have your application on file and as per our conversation this morning, I have enclosed an Improvement Permit for Repair that should be installed by **February 14, 2014**. That date is in conjunction with the Intent to Suspend violation which you have received from the Food & Lodging Program of the Harnett Co. Health Department. In addition, I advise that the septic and pump tanks be pumped on a regular basis to prevent surfacing.

You are hereby notified that you are violating the Rules and Regulations adopted by the North Carolina Commission for Health Services in accordance with requirements of Article 11 Chapter 130A-335 (a) of General Statutes of North Carolina. Any person owning or controlling a residence, place of business, or place of public assembly containing water using fixtures connected to a water supply source shall discharge all wastewater directly to an approved wastewater system permitted for that specific use. A wastewater system may include components for collection, treatment and disposal of wastewater.

You are required to correct this problem within the date as specified above. Please be advised that any action you may take without an improvement permit does not absolve you of the responsibility for correcting this public health problem, according to health department standards. The continuation of this violation may constitute a health hazard, and **if you do not comply within the allotted time frame we will be forced to obtain legal action.**

I can be contacted at 893-7547 Monday-Friday, from 8:00-9:00 a.m.

Sincerely,



Bryan McSwain, R.E.H.S.
Environmental Health Program Specialist
Harnett County Department of Public Health
Environmental Health Section

BM/sgs

Enclosure(s)

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

John Homan
 12638 NC Hwy 42
 Holly Springs, NC
 27540

2. Article Number
 (Transfer from service label)

7012 3460 0001 6151 9185

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X

Nick Taylor Agent
 Addressee

B. Received by (Printed Name)

Nick Taylor

C. Date of Delivery

1-24-04

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type

- Certified Mail Express Mail
- Registered Return Receipt for Merchandise
- Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

7012 3460 0001 6151 9185

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
 (Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE

| | |
|---|----|
| Postage | \$ |
| Certified Fee | |
| Return Receipt Fee (Endorsement Required) | |
| Restricted Delivery Fee (Endorsement Required) | |
| Total Postage & Fees | \$ |

Postmark
Here

Sent To

Homan, John

Street, Apt. No.,
or PO Box No.

City, State, ZIP+4