Hannett County Date 5:30-02

MALFUNCTIONING SYSTEMS

Fill out this section at the time the Malfunction is Evaluated and a Permit Issued or other Remedy Proposed

For the SYSTEM that Malfunctioned or was Damaged or Destroyed								Replacement
System Code	Age	Was it Initial or	Distribution System	Soil Texture	Design Flow	Cause Code	Location	System or Remedy Code
Regh	58/10	Replan	in	SL-CL	240	Pge	Bu STA	25%
		,	12			/	yaras -	
ļ								
					-			
			,		-			
		2						
	-							