

COMMENTS:

Bm 9/9/2013 Met with Mr. Karas + Jay Adcock. The system has dried up so effluent surfacing. The ditch on the right hand side was clogged & water was backed up. It was suggested the Mr. Karas have the ditch cleared which will allow the water to flow.