

SITE WAS VISITED ON 1/17/02 BY OLIVER TOLKSOORE. THE DISTRIBUTION BOX WAS TILTED DIRECTING ALL THE FLOW TO THE BOTTOM LINE. THE DISTRIBUTION BOX WAS REPLACED. THE FLOW WAS SET TO REDUCE THE FLOW TO THE BOTTOM LINE. LANDSCAPING WAS STILL REQUIRED TO PREVENT FURTHER EROSION FROM THE DRAIN LINES AND COVER TANK AND DISTRIBUTION BOX. NO PERMIT REQUIRED FOR ACTION TAKEN.