

### Harnett County Central Permitting

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

#### Certification of Work Performed By Owner/Contractor (Individual Trade Application)

Owner (s) of Structure: Holly Gardner Phone: 919-669-6291

Owner (s) Mailing Address: 2265 Benson Rd  
Angier N.C. 27501

Land Owner Name (s): Holly Gardner Phone: 919-669-6291

Construction or Site Address: 2265 Benson Rd. N.C.

PIN # \_\_\_\_\_ Parcel # \_\_\_\_\_

Job Cost: \$1,000.00 Description of Work to be done change electrical service from overhead to underground service

Mechanical: New Unit With Ductwork  New Unit Without Ductwork  Gas Piping  Other

Electrical\*: 200 Amp <200 Amp  Service Change Service Reconnect  Other   
\* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap  Number of Baths  Water Heater

Specific Directions to Job from Lillington:  
take 210 to Angier - right on Highway 55 - go 2 blocks and turn left on Benson Rd - go 1/2 mile, house on left at corner of Old Stage and Benson Rd

Subdivision: \_\_\_\_\_ Lot #: \_\_\_\_\_

I Teddy Dodson will provide the electrical labor on this structure.  
(Contractors Name) (Trade)

I am the building owner or my NC state license number is \_\_\_\_\_, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

Teddy L. Dodson 919-306-6379  
Contractor's Company Name Telephone  
6117-A Applewhite Rd Wendell, N.C. reddodson08@gmail.com  
Address Email Address  
12616-L  
License #

Structure Owner / Contractor Signature: Stephen Dean Date: 2-10-2022

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

\*Company name, address, & phone must match information on license