

Harnett County Central Permitting

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

Certification of Work Performed By Owner/Contractor (Individual Trade Application)

Owner (s) of Structure: Arthur Brown Phone: 919-627-2734

Owner (s) Mailing Address: 609 N. 16th Street
Erwin, NC. 28339

Land Owner Name (s): Arthur Brown Phone: 919-627-2734

Construction or Site Address: 609 N. 16th Street, Erwin, NC

PIN # _____ Parcel # _____

Job Cost: \$1,400 Description of Work to be done Gas piping & HVAC & repairs
to get final for homeowner due to installing contractor being
un-licensed

Mechanical: New Unit With Ductwork New Unit Without Ductwork _____ Gas Piping Other _____

Electrical*: 200 Amp _____ <200 Amp _____ Service Change _____ Service Reconnect _____ Other
* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap _____ Number of Baths _____ Water Heater _____

Specific Directions to Job from Lillington:
see attached

Subdivision: _____ Lot #: _____

I Brent Beasley / Hugh Smith will provide the HVAC / Electrical labor on this structure.
(Contractors Name) (Trade)

I am the building owner or my NC state license number is 9497 / 7564-1, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

Beasley's Heating & Air, Inc / Hugh Smith Electrical 919-894-4248
Contractor's Company Name Telephone
57 WC Beasley Lane, Coats, NC / 817 Merry Street, Dunn, NC beasleyshvac@aol.com
Address Email Address
9497 / 7564-1
License #

Structure Owner / Contractor Signature: [Signature] Date: 10/02/2020

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

***Company name, address, & phone must match information on license**