

Application # \_\_\_\_\_

**Harnett County Central Permitting**

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

**Certification of Work Performed By Owner/Contractor**

(Individual Trade Application)

Owner (s) of Structure: Jonathan Elkins Phone: (919)628-3702

Owner (s) Mailing Address: 2005 Ebenezer Church Rd  
Coats, NC 27521

Land Owner Name (s): Jonathan Elkins Phone: (919)628-3702

Construction or Site Address: 2005 Ebenezer Church Rd, Coats, NC

PIN # \_\_\_\_\_ Parcel # \_\_\_\_\_

Job Cost: 5000<sup>00</sup> Description of Work to be done Change out 4 Ton  
Heat Pump w/ 10 kw heat strip

Mechanical: New Unit With Ductwork \_\_\_ New Unit Without Ductwork  Gas Piping \_\_\_ Other \_\_\_

Electrical\*: 200 Amp  <200 Amp \_\_\_ Service Change \_\_\_ Service Reconnect \_\_\_ Other \_\_\_  
\* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap \_\_\_ Number of Baths \_\_\_ Water Heater \_\_\_

Specific Directions to Job from Lillington:  
\_\_\_\_\_  
\_\_\_\_\_

Subdivision: \_\_\_\_\_ Lot #: \_\_\_\_\_

I John Friend will provide the Mechanical labor on this structure.  
(Contractors Name) (Trade)

I am the building owner or my NC state license number is 31183, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

All Pro Mechanical  
Contractor's Company Name  
238 Lester Houston Rd  
Address  
Pink Hill  
31183  
License #

(252) 714-9783  
Telephone  
allpromech2020@gmail.com  
Email Address

Structure Owner / Contractor Signature: [Signature] Date: \_\_\_\_\_

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

\*Company name, address, & phone must match information on license