

### Harnett County Central Permitting

PO Box 65 Lillington, NC 27546 - Ph: 910-893-7525 - Fx: 910-893-2793 - www.harnett.org/permits

#### Certification of Work Performed By Owner/Contractor (Individual Trade Application)

Owner (s) of Structure: Virginia and Mitchell Jackson Phone: 919-880-7522

Owner (s) Mailing Address: 1755 Wade Stephensen Rd  
Holly Springs, NC 27540

Land Owner Name (s): Same Above Phone: \_\_\_\_\_

Construction or Site Address: Same Above

PIN # \_\_\_\_\_ Parcel # \_\_\_\_\_

Job Cost: \$13842.00 Description of Work to be done Bathroom Remodel Tub to Shower

Mechanical: New Unit With Ductwork \_\_\_ New Unit Without Ductwork \_\_\_ Gas Piping \_\_\_ Other \_\_\_

Electrical\*: 200 Amp \_\_\_ <200 Amp \_\_\_ Service Change \_\_\_ Service Reconnect \_\_\_ Other \_\_\_  
\* For Progress Energy customers we need the premise number

Plumbing: Water/Sewer Tap \_\_\_ Number of Baths \_\_\_ Water Heater \_\_\_

Specific Directions to Job from Lillington:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subdivision: \_\_\_\_\_ Lot #: \_\_\_\_\_

I ReBath of the Triangle will provide the Installation labor on this structure.  
(Contractors Name) (Trade)

I am the building owner or my NC state license number is 29933, which entitles me to perform such work on the above structure legally. All work shall comply with the State Building Code and all other applicable State and local laws, ordinances and regulations.

ReBath of the Triangle  
Contractor's Company Name  
8817 Westgate Park Dr # 112 Raleigh, NC 27617  
Address  
29933  
License # \_\_\_\_\_

919-215-6026  
Telephone  
george@trianglererebath.com  
Email Address

Structure Owner / Contractor Signature: \_\_\_\_\_ Date: 10/7/21

By signing this application you affirm that you have obtained permission from the above listed license holder to purchase permits on their behalf. If doing the work as owner you understand that you cannot rent, lease or sell the listed property for 12 months after completion of the listed work.

**\*Company name, address, & phone must match information on license**