

November 7, 2007

LeLym Castellanos Alvarado 481 McDuffie Rd Cameron, NC 28326 Repuir appoint of 2/28/07

www.harnett.org

Harnett County Government Complex 307 Cornelius Harnett Boulevard Lillington, NC 27546

> ph: 910-893-7547 fax: 910-893-9371

RE: Existing Septic System Inspection HTE #07-5-18564 - Existing tank #07-5-18563 - New Septic System

Dear Mr. Alvarado,

An attempt was made to evaluate your property for the purpose of issuing an Existing Tank Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Uncover outlet lid on septic tank and break seal
- 2. Have system pumped out
- \_\_\_\_\_ 3. Replace sanitary T

X 4. Other – See below

The existing septic system does not meet requirements, therefore it is denied. You need to fill out a repair application for that site at our office (no charge). We need to correct the problem with the existing system before we work on second site. You need to have a surveyor locate all property iron corners and exactly flag side lines. This is a small, tight lot and I need to know exactly where property corners and lines are.

Your application will be put on hold until the selected items above have been addressed. When completed call 893-7547 to confirm that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,

Joe West, R. S.

Environmental Health Specialist

Harnett County Department of Public Health

**Environmental Health** 

JW/ss

Copy - Central Permitting