

May 3, 2016

Thomas O'Neal Austin
309 B J Lane
Holly Springs, NC 27540

RE: Existing Septic System Inspection HTE# 16-5-38489

Dear Mr. Austin,

An attempt was made to evaluate your property for the purpose of issuing an Existing Tank Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Uncover outlet lid on septic tank and break seal (*\$25.00 fee incurred*)
- 2. Have system pumped out
- 3. Replace sanitary T
- 4. **Other – Replace the lids including handles, on your septic tank.**

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



James E. Manhart, III, R.E.H.S.
Environmental Health OSWW Specialist
Harnett County Department of Public Health
Environmental Health

JEM/sgs
Copy - Central Permitting