



System: -----  
 Repair: —————

- \*Keep tanks and drain lines 10' from property lines.
- \*Not a survey.
- \*Not a guarantee of a septic permit.
- \*Keep supply lines >5' from property lines.
- \*Some lines are flagged longer in the field than lengths indicate.
- \*No grading septic area.

GRAPHIC SCALE  
 1" = 50'



System: Gravity to Serial Dist.  
 Lines: 5-7, (350')  
 Accepted Status System  
 0.35 Soil LTAR  
 24" Trench Bottom

Repair: Gravity to Serial Dist.  
 Lines: 1-4, (280')  
 0.35 Soil LTAR  
 T&J Panel 50% Reduction



Central Carolina Soil Consulting, PLLC  
 1900 South Main Street, Suite 110  
 Wake Forest, North Carolina 27587  
 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout  
 Lot 16, Masons Pointe Subdivision  
 Harnett County, North Carolina

Job# : 2031
Drawn By : AH
Date : 11/11/2019
Revision: